10

1

MDECLASSIFIED

Contraction of the second second	400A Hours 1 April	1945. To: 012400A
I. :	INISTRATION	
· A .		er Combat Group
1. A. A.	Coordinates: <u>596970</u> Vie	
В.		
	Bn Hqs and H & S Co, 2826th Engr Bn moved HAUSEN.	to 629964 vic NECKAR-
III. (OPERATIONS.	
	Roads: Constructing barricados on each : 586979.	side of blown bridge at
D.	Miscellaneous engineering work.	
	Maintaining approaches to Treadway bridge	at 5300 Manheim. 1 squad
	"C" Co. maintaining bridge at 699909 (Hear	
	Engr C Bn assignment. 2828th Engr Bn unle	
	at 578973.	
E.	Disposition of troops during period.	
		up bivouac and maintain-
		baches to bridge in
	Mannheim.	
		barricades and un-
	Toadrug	Bailey Bridge Train.
TV	EQUIPMENT AND SUPPLIES	
	Water Points in Operation.	
oordina	tes Vicinity Source (Quality Max Quantity
62397		Clear 15 GPM
	and the second se	
	1.2	4 9 Lockey
	110	first Lochery
		PH G. GODFREY,
	Capt., 3	oth Engr Combat Group,
		S-3
eja	LASSIFICATION CHANGED TO:	
·	CHANGED TO:	.16
	BY AUTOCANCELLED	12 119
	BY AITTING	3''
	OF THE ADDREN	1 dies
	BY AUTHONIN OF THE ADDITANT G	ENERAL MADU
	STANDING COMMITTEESS	ENERAL Master
	the second se	America
	AL AL	



Period	Covered: From: 01	.2400 A	To: 022400 A	
I.	ADMINISTRATION.			
	Headquarters reporting	: 36th En	gineer Combat Group	
	Coordinates:	596970	Vic SECKENHEIM	
III.	OPERATIONS.			
в.				
	2828th Engr Bn erected	barricade at	blown bridge 650815. I	Erected
	borricade at blown bri	dge 637748.		
D.	Miscellaneous Engineer	ing Work.		
	2827th Engr Bn maintai	ning approache	s to treadway bridge a	at 5300
	MA THEIM, and maintain	ing bridge at	699909 (Heavy Ponton).	All
	co panies had details	with trucks go	to SCHERFERSTADT and	pick up
	Bailey bridge, haul it	to west of th	e airfield at MANNHEIN	l, and
	unload it. 2828th Eng			
	from SCHERFERSTADT 470		d 570973. Removed trol	lley
	wires from roadway at			
E.		During Period.		
	Unit		Task	*
	2826th Engr C Bn	Trainir	-	
	2827th Engr C Bn		ning approaches to br:	idge and
			Bailey bridge.	
	2828th Engr C Bn	Loading	; and transporting Bail	ley bridge

/ewh



And a second sec	AOO	He	ours	3 April		1945.	
Period Co	overed:	From:		022400A	To:	232400 <i>f</i> .	and the second second
	APMINIST	and a state of the second s					
Α.			eporting:		neer Comba	t Group	
	Coor	'd: 5969'	76	Vic. SECKENH	EIM		
III.	O RATIC	and the second				101000 1	
D.				n charge from RR			
				d treadway bridg			
				l blown bridges			
				99909 Vic HEIDEL			
				man Ponton train			55
				lley wires from	roadway at	601967.	
E.			Troops.				
		Init			Tas	k	
		Engr C 1		Removed demolit	ion from R	R Bridge, tra	lining.
	2827th	Engr C	Bn	Guarding,train			
	- april	·V		treadway bridge		ing approache	es to
	ododu			heavy ponton br	·idge.		
	2828th	Engr C	Bn	Training			
	TOTITO		IDDI TOO				24
IV.	EQUIPMEN	the second se	and the second se				~ 1
A •			n Operatio		land of O	21 000 0-+-	1+
				C NECKARHAUSEN C	closed at U	91000. 10ta.	l out-
-			11,665 gal	lons.	1		
В.	DeadLir	ned Vehi	cles:				

B. Deadlined Vehicles:

Company C, 2826th Engr Bn - $12\frac{1}{2}$ T Dump Truck in Battalion Repair Shc C. Change in Status of Major Equipment:

2826th Engr ^Dn picked up four dry loads of Treadway Bridging from 196th Engineers.

Note: B Co, 2827th Engr Bn was stopped by 254th Inf. from erecting a barricade around bridge at 521002 vic MANNHEIM. The 254th Inf. had orders from A.M.G.

RALPH G. GODFREY, 1 co

Capt., 36th Engr Combat Cp., S-3 AND DECLASSIFIED

0

ENGINEER SITUATION REPORT

	Hours	4 April 1945.
Period	Covered: From: 03240	
The second		
I. I	DMINISTRATICN.	
A.		36th Engineer Combat Group
24		5976 Vic SECKENHEIM
в.		ion of Companies or Battalions.
1	2826th Engr Bn	MAL AND A MALE AND A
W.		715783 vic WIESLOCH. "A! Co. moved to 729-
		moved to 728763 vic DIELHEIM. "C" Co. mov-
	ed to 732785 vic BAIERTAL.	
III.	OPER TIONS.	
A.	Brige, bypass, or ford co	onstruction, repair and maintenance.
	Coordinates Vicinity	Type Lgth Cl Lanes % Comp. Date Con
		Fimber 20' 40 10 051200
		nber-Trestle-30' 40 2 25
		nber-Trestle-48' 40 12 33
В.	Roads.	
		a assigned sector of roads 700910 to 84094
		lling pot holes and craters. Maintained rou
	MANNHEIM 522985 to DECKAR	GEMUND 770888. Road from 840947 HIRSHBORN
	to CR vic MOSSBACH. Genera	
D.	Miscellaneous Engineering	
		g approaches to ponton bridge at 699902 vi
		ting stockade vic HEIDELBURG. Filled in two
		icles from road, maintaining Treadway brid.
	at MANNHEIM.	
E.	Disposition of Troops Dur:	ing Period.
	Unit	Task
	2826th Engr C Bn	Moving and constructing timber bridge.
	2827th Engr C Bn	Maintaining road and guarding captured
		enemy equip. 590865 SCHWETZINGEN and
	· · · · · · · · · · · · · · · · · · ·	580825 FRIEDRICHSFELD, constructing
		bridge at 799898, maint. approaches to
	· · · · · · · · · · · · · · · · · · ·	ponton bridge, constructing stockade,
		filling in bomb craters and clearing
		vehicles from road.
	2828th Engr C Bn	/ Training.
IV.	EQUIPMENT AND SUPPLIES:	4 A A A A A A A A A A A A A A A A A A A
	Org. Item Ca	use <u>Disposition</u> <u>Action require</u>
	282(th E a T C&R (2)	Bn repair repairs
	8820th E 22 T Dump Truck	Bn repair repairs
		1 2 2 2
		a planter,
		RALPH. G. GODEREY
		Capt., 36th Engr Combat Gp.,
		S - 3
	/ewh	



ENGINEER SITUATION REPORT

	400 A Hours <u>5 April</u> 1945.
Period	Covered: From:O42400 ATo:O52400 A
I.	ADMINISTRATION.
Α.	
	Coordinates: 014809 Vic NECKARZIMMERN
В.	Change in status or location of Battalions or Companies:
	2827th Engr Bn
	Bn Hq moved to 905970 vic EBERBACH. "B" Co. moved to 906971 vic B"R-
	BACH. "C" Co. moved to 907969 vic EBERBACH.
	282 th Engr Bn
	H&S Co. moved to 014808. "A" Co. moved to 018808. "B" Co. moved to 020
	804. "C" Co. moved to 016841.
	Grop Has, 36th Engr C Group moved to 014809 vic NECKARZIMMERN.
тт	INFORMATION ON CBSTACLES ENCOUNTERED.
	7
A.	
	Coord Vicinity Crossing Type Lanes Cl No Leth Gap Wet Gap 830708 SINSHEIM River Stone 2 40 441 271
	830708 SINSHEIM River Stone 2 40 441 271 860785 WAIBSTADT River Stone 2 40 341 341
в.	Road blocks.
	CoordinatesVicinityTypeDisposition938708GROMBACHFallen TreesRemoved
	938708 GROMBACH Fallen Trees Removed
	938708GROMBACHFallen TreesRemoved855715STEINSFURTAbatisRemoved000660KIRCHHAUSENAbatisRemoved
	000660 KIRCHHAUSEN Abatis Removed
1. W.	Also removed 12 autos used as road blocks between STEINSFURT 855715
7.5.*	and KIRCHHAUSEN 000660.
III.	OPERATIONS.
A.	Bridge, bypass, or ford construction, repair and maintenance.
	Coord. Vicinity Type Lgth Cl Lanes % Compl Date Compl.
-	850730 ROHRBACH Timber 201 40-70 2 100 051200
	789898 DILLSBURG-Timber Trestle 30' 40 2 100 051900
	799904 NECKER- Timber Trestle 481 40 11 100 051900 STEINBACH
в.	989830 NECKARELZ-Floating Tread 2641 40 Maint. and improving approache Roads.
ъ.	2826th Engr Bn maintaining roads and sweeping for mines from KIRCHARD
	915680 to BAD WILPFEN 030708. Used 1 load of fine gravel. No mines
	located. Work 90% Completed. 2827th Engr Bn maintained roads in acli
	ed sector from 700910 to 840947. to 522985 MANNHEIM to 770888 NECKAR-
	GEMUND to 840947, HIRSHORN to CR 993833 vic MOSSBACH. Filling in crate
	and potholes and opening to two way traffic.
D.	Missellaneous Engineering Work.
	2820th Engr Bn road and engineer material reconn within the MAUER -
	WEISLOCH - MIBSTADT triangle. One stone quarry located at 824811.
	Two stone quarries located at 824807 vic ESCHELBRONN. Filled craters
	at 856714 and 860709. Work completed. Loaded one trailer w/"I" beams.

ALACOOL	CLASSIFIED
MPU	725017
unhority	10001
And	MANA, Data

Miscellaneous Engineering Work (Cont'd) D. .

2827th Engr Bn maintaining approches to ponton bridge at 699902 vic HEIDELEURG, also constructing stuckade vic HEIDELBURG. Maintaining Treadway bridge at MANIMHEIM. Guarding enemy equipment vic SCHWETZIN-GEN 590865 and FREIDRICHSFELD 580825. <u>2828th Engr Bn</u> constructing signs, loading rock for approaches to Treadway bridge, and guarding electrical station.

. : . .

the spirit of a spirit age of the spirit

- E. Disposition of Troops During Period. Unit
 - 2826th Engr C Bn Cleared road blocks, road maintenance, "roconn of road, and constructing Timber 1.15 bridge. Guarding enemy equipment, maintaining 2827th Engr C Bn

Froad, constructing bridge at 799898, maintaining approaches to ponton bridge, constructing stockade, moved to new area. 2828th Engr C Bn Construction of bridges and signs, guard

Task

- and the second
- on electric station, and moving.
- IV. EQUIPMENT AND SUPPLIES.

C. Changes in status of major equipment. Org. Item Cause 2826th E 2 Ton C&R Burned Action Required Disposition Salvage Sector 1 -Inclosures: <u>1</u> Engineer Reconnaissance Report. <u>1</u> Road Condition overlay. 1 at man palake 1279月1日建筑中市中市中市市 RALPH G. GODFREY TIME SHI MICH C Capt., 36th Engr Combat Gp., S-3 /ewh and an are to an a contract HE GOVERNMENT and the set of the set of the set of the set of the NYCE PROVIDENT OF THE SECOND CONTRACTOR OF THE NO WEARANT AND AND AND A 1. Millingertart

Lables (concept 11.00)

STALL HE HERE



HEADQUARTERS 36TH ENGINEER COMBAT GROUP

6 April 1945

Stores

ENGINEER RECONNAISSANCE REPORT

The following listed material was located in the Stolberg Zink Works at 715783 vic WIESLOCH (2826th Engr Combat Bn Bivouac Area) Bunches - Electric Saps - German (200 in bunch) 50 Boxes German Caps -2 Rolls - 6 Guage wire netting 26' long 10. Cross-cut Saw blades 50 10" Rubber Belting 1 Roll - Fine Mash Wire 30" long 20' 1" Rubber Hosing 3 Rolls - German Sommerfeld Matting 420 120 lbs - leather tacks 30 pr - Rubber Boots - assorted sizes 50 WWW Type Belts 60 Shovel Heads Rolls - No. 10 wire Spools - 2" Steel Cable (1000 meter spools) 3 2 2 Roals - 3/8" Cable: Rolls - Galvanized Wire - sizes from No. 4 to 10 8 2 Rolls - Copper Wire - size No. 10 150 Push Brooms w/o handles 20 Rolls - Wrapping Cord 400 Cable Clamps - 9/16* 400 Cable Clamps - Size 7/16" Buck Saws 4000 feet - Pipe - sizes from 1/4" to 2" 4 pieces - Steel Sheeting 4 x 8 x 1/8" 60 pieces - Steel Sheeting 4 x 8 x 1/16" Oxygen Tanks 4 pieces - Steel Sheeting 4'x 8'x 1/4" pieces - Steel Sheeting 4'x 8'x 5/16" 4 8 Long Spout Oil Cans Washers - Unlimited Supply and assortment Welding Rods - Unlimited Supply Rubber Gaskets - Assorted Sizes Time Fuzes - Unlimited Supply Valves - Assorted Sizes Nut Wrenches - Assorted Sizes Drills - Sizes from 9/16 to 1 1/2 Rivets, Screws, Nuts, Bolts, Unions, Couplings, Reducers, -Unlimited supply and assorted sizes.



話

Scrap Iron and Angle Iron - assorted sizes and lengths. 50 Point Drills 7/16" Shaft 1 Air Hammer

(SOURCE: 2826th Engineer Combat Bn)

The following listed timber was located at 874662 vic of ITTLINGEN.

SIZE	AMOUNT	LOCATION
2" x 4" x 16' - 20' - 18' 3" x 8" x 16' - 18' - 20' 2" x 8" x 16' - 18' - 20' 2" x 8" x 16' - 18' 20' and 2 1" x 4, 1 x6, 1x8x16-18-20' 4" x 4" x 14'	2500 pos 500 pos 2 x 6 700 pos 1500 pos 50 pos	Ittlingen 874662 # # # # # # # #

MMDECLASSIFIED

MANA, Data

)

21	00 A Hours 6 April 1945.
Period	Covered: From: 052400 A To: 062400 A
Ί.	ADMINISTRATION.
	Headquarters reporting:
	Coordinates: 014809 Vic NECKARZIMMERN
В.	Change in status or location of Battalions or Companies:
	2826th Engr Bn
	Bn Hqs and H&S Co. moved to 992720 vic RAPPENAU. "A" Co. moved to
	925681 vic KIRCHARDT. "B" Co. moved to 062642 vic NECKARGARTACH.
	"C" Co. moved to 025671 vic BIBERACH.
	2827th Engr Bn "A" Co. moved to 003838 vic NECKARELZ.
	X OU. MOVEL 10 00 30 VIC MICHAILEDS.
II.	INFORMATION CH OBSTACLES ENCOUNTERED.
	Road Blocks.
	Coordinates Type Disposition
	023848 to 149031 Wrecked vehicles & fallen trees Removed
	OPERATIONS.
A.	Bridge, bypass, or ford construction, repair and maintenance.
	Coord. Vicinity Type Leth Cl Lanes & Comp Date Comp
	989830 NECKARELZ Floating Tread. 264' 40 Maint. & improving approach 24 Hour maintenace.
в.	Roads.
	2826th Engr Bn filling pot holes, clearing drainage ditches, and re-
	moving debris on road stretch from 856713 vic STEINFURT, southeast
	to 000668 vic KIRCHAUSEN. Approximately 15 loads of rock and brick
	used for above road stretch. Maintained and cleared for mines road
	stretch from 915680 vic KIRCHARDT to 030708 vic BAD WIMPFEN. Work
	completed. <u>2827th Engr Bn</u> maintained HEIDELBERG road from HIRSCHCRN
	840947 to CR at 993833 vic MOSSBACH. Relieved at 061200 by 540th Engr 2: 38th Engr Bn improving and maintaining road for 112th Evac Hospital
	s arting at 011851 to 001859 to 001861 to SCHRECKHOF 995858 to 003851
	to 995843.
D.	Miscellaneous Ingineering Work.
	2826th Engr Bn supporting 325th Engrs ferrying supplies to Infantry
	across Neckar River at 069646 vic NECKARGARTACH (HEILBRONN bridgehead
	2827th Engr Bn guarding bridge at DILLSBURG, guard being relieved at
	061200. Maintained approaches to ponton bridge at 699902 vic HEIDEL-
	BERG. Constructed guard rails and dressing up approaches to bridge at 789898. Guards on enemy equipment at SCH/ETZINGEN and FREIDRICHS-
	TELD relieved. 2828th Engr Bn constructing PW inclosure at 022847.
	checked underground aircraft factory at 985831 for hidden charges. No
	charges found. D-7 working with 1271st Engrs making approaches to
	bridge at 089755. Constructing and painting signs, work completed by
	071800. Guarding power stations at 023848 and 015807.

· · · · ·

; ; ; ; ;

MADA Dale

Disposition of Troops During Period. Unit Task E.

in all a series of a

· · · · ·

1

nalizano sua presidente de cargo a constante de cargo a constante de constante de constante de constante de const Presidente de constante de constan

a manada a construction and a second and appendix a construction of the second statements

A Herddrever of a state of a st

State Assesses

The states of the second

- 2 -

 $\frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{$

2826th Engr C Bn

SALONO TODA D. MAR. and an and a second s 2828th Engr C Bn an ggerer.

2827th Engr C Bn

the support

9.00

onder en maker in Prezententen

The film of the second second

Perion Screept. From the Science of Science

all the second second

1 10

10 . .

Road maintenance, ferrying supplies, a.d. moving.

The state with a contract the state of the state of the

A Sharen in the second

1 North Minister

States a get - Horard

Road maintenance, constructed guard rails on bridge at DILLSBURG. Relieved of all on pridge at DILLSBURG. Relieved of all guards, moving. Road maintenance, constructung PW enclos-ure, guard details

.

17 7 395

RALPH G. GCDFREY RALPH G. GCDFREY Capt., 36th Engr Combat Gp., S-3

UND	ECLASSIFIED
uthority	735017
1D	MANTA, Data

ENGINEER SITUATION REPORT

the second secon	2400 A Hours 7 April 1945.
Period	Covered: From: 062400A To: 07:400A
I.	ADMINISTRATION.
A.	Headquarters reporting: 36th Engineer Combat Group
	Coordinates: 014809 Vic NECKARZIMMERN
C.	Engineer Personnel Casualties: (KIA) (WIA) (MIA)
	(Off)1st Lt M. C. Callahan (Gunshot) 1
III.	OPERATIONS.
A.	Bridge, bypass, or ford construction, repair and maintenance.
	Coord. Vicinity Type Leth Cl Lanes % Comp. Date Comp.
	989830 NECKARELZ Floating Tread 264' 40 1 Maint. & improving approac
в.	Roads.
	282. "In Engr Bn improving and maintaining road for 112th Evacuation Hos-
	pital, starting at 011851 to 001859 to 001861 to SCHRECKHOF 995858 to
	003831 to 995843.
D.	Miscellaneous Engineering Work.
	2826th Engr Bn made recom for critical bridge sites which require
	guarding. 24 hour guard assigned to following bridge sites: 850729 (ROHRBACH), 855717 STEINFURT, 010654 KIRCHHAUSEN, 858710 STEINFURT (cu
	vert). Prepared far shore abutment for Treadway bridge at 080614 HEIL
	BRONN. Cleared lateral road of debris to exit at 076614 HEILBRONN.
	Cleared main road to bridge site from 057613 HEILBRONN to 078614 HEIL-
	BRONN. Filled one crater at 075614, used one load of rock. 2827th
	Engr Bn Policed lumber etc. at bridge site 789898 and hauled lumber to
	2749th Engineer dump. 2828th Engr Bn constructed PW enclosure at 022-
	847, completed 071200. Constructing and painting signs, complete 071800
	Guarding power stations at 023848 and 015807. Guarding entrance to underground factory at 015813.
E.	
1.	Unit Task
	2826th Engr C Bn Guarding critical bridge sites, preparing
	far shore abutment for Treadway bridge at
	080614, road maintenance and clearance.
	2827th Engr C Bn Policed up lumber and hauled it to 2749th
	Engr dump.

2828th Engr C Bn

Maintenance of bridge, constructed PW cage, guards at power stations and underground factory.

• ()

RALPH G. GODFREY Capt., 36th Engr Combat Gp., S-3

/ewh



See.

2400AHours8 April1945.Period Covered: From:072400ATo:082400AI. ADMINISTRATION.	
I. ADMINISTRATION.	
A. Headquarters reporting: 36th Engineer Combat Group	
A. Headquarters reporting: <u>36th Engineer Combat Group</u> Coordinates: <u>014809</u> Vic NECKARZ	IMMERN
B. Change in status or location of Companies or Battalions.	
Co. A, 2826th Engr C Bn moved to 033652 vic KIRCHHAUSEN.	
Bn Hq, 2827th Engr C Bn moved to 403978 vic BOBSTADT	
A Co, 2827th Engr C Bn moved to 405982 vie BOBSTADT B Co. 2827th Engr C Bn moved to 405982 vie BOBSTADT	· · · · · · · · · · · · · · · · · · ·
B Co, 2827th Engr C Bn moved to 345981 vic BCBSTADT C Co, 2827th Engr C Bn moved to 345917 vic CBERNDORF	
000, ECCIVIT ENER O BIT MOVED DO 34591 VIC OBLEMPORE	
II. INFORMATION ON OBSTACLES ENCOUNTERED.	the Barrow
A. Bridges or culverts: (a) blown (b) less than Cl 40. (c) car	using
traffic restrictions due to width. Spans	· 11
0. Coordinates Vicinity Crossing Type Lanes Cl No. Leht Gap	Wet Gap
Honebach masonry arch 2 120' each	span
This stream can be forded. B. <u>Road Blocks</u> :	for the
Coordinates Type VDisposition	· .
059615 Steel rail ties embedded in 1 Demoltshedd	
ground	A deres
059615 Steel rail ties embedded in Demolished ground 063613. Road Crater. Filled with 30 lo	ads of
rock	and the second
070612Road CraterFilled with earth440943Felled treesRemoved42948Felled treesRemoved	10 201
440943 Felled trees Removed	the second
4.2948 Felled trees Removed	
D. <u>Miscellaneous obstacles, newtonemy coulpment or methods</u> .	OFFERE
2826th Engr C Bn JaBnomy explosive found under culvert at vic FURFELD - removed.	955080
VIC FORFELD - TEMOVED.	
III. OPERATIONS.	
A. Bridge, bypass, or ford construction, repair and maintenan	ce.
Coord. Vicinity Type Leth Cl Lanes & Comp Dat	
989830 NECKARELZ Floating Tread. 2641 40 1 Maint. & impr	oving
approaches, 2	4 hour.
B. Roads.	
2826th Engr Bn cleared, improved and widened lateral road	leaving
bridge on east (far) shore at 079614 vic HEILBRONN. Constr	ucted
new approach leaving bridge on east (far) shore, from 0796	14 VIC
HEILBRONN leading up to main highway at 079615 vic HEILBRO 2827th Engr Bn initial recomm made and the bad spots are b	eine
worked on now. Roads assigned as per overlay attached. 28	28th
Engr Bn filling crater in road at 035766, work completed t	y 09180



and the second	
D. Miscellancous Engineering Work.	
2826th Engr Bn Located two stone quarries and secondary rock crushers	
at 943740 vic CBERGIMPERN. Critical bridge guards relieved at 081130.	
Directing tank traffic at bridge site. <u>2828th Engr Bn</u> constructing	
addition to PW enclosure at 022847. Completed 081200. Picking up	
decking from vicinity of airfield at 565975. Obtaining L-beams from	
rail yard at 560960. Constructing and painting signs, complete 081200.	
Guarding power station at 015807. Guarding entrance to factory at	
ol 313.	
E. Disposition of Troops During Poriod.	
Unit Task	1
2826th Engr C Bn	
guarding critical bridges, road mainten-	
ance and improvement, constructing road	
connecting cast bridge approach to main	
highway, maintained bridge approach.	
2827th Engr C Bn Noved and set up bivouac, removed two	
road blocks.	
2828th Engr C Bn Bridge maintenance, guards at power light	
and underground factory, constructed PI	
cage, filling craters.	
Cage, IIIIIng Craters.	
cage, illing craters.	
IV. EQUIPMENT AND SUPPLIES.	
· 如何,如此,你们就是我们就是你们,那么是你们不能的你的你?""你们,你能能能。"	
IV. EQUIPMENT AND SUPPLIES. A. Water points in operation.	
IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation</u> . <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u>	
IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation</u> . <u>Coord. Vicinity Source Quality Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited	
<pre>IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord. Vicinity Source Quality Max Quantity</u> 014807 NECKARZIMMERN River Muady Unlimited C. Change in status of major equipment.</pre>	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River <u>Muady</u> Unlimited C. <u>Change in status of major equipment</u>. <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 	
<pre>IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord. Vicinity Source Quality Max Quantity</u> 014807 NECKARZIMMERN River Muady Unlimited C. Change in status of major equipment.</pre>	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment</u>. <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs 	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River <u>Muady</u> Unlimited C. <u>Change in status of major equipment</u>. <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment</u>. <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs 	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment</u>. <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs 	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment</u>. <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs 	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover En shop Repairs Inclosures: <u>1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation</u>. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment</u>. <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs Inclosures: <u>1</u> Road assignment overlay. RALPH G. GODFREY. 	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max QUantity</u> 014807 <u>NECKARZIMMERN</u> River <u>Muddy</u> Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover <u>Bn shop</u> <u>Repairs</u> <u>Inclosures: 1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation.</u> <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs Inclosures: <u>1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. Water points in operation. <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max QUantity</u> 014807 <u>NECKARZIMMERN</u> River <u>Muddy</u> Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover <u>Bn shop</u> <u>Repairs</u> <u>Inclosures: 1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation.</u> <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs Inclosures: <u>1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation.</u> <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs Inclosures: <u>1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation.</u> <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs Inclosures: <u>1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation.</u> <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs Inclosures: <u>1</u> Road assignment overlay. 	
 IV. EQUIPMENT AND SUPPLIES. A. <u>Water points in operation.</u> <u>Coord.</u> <u>Vicinity</u> <u>Source</u> <u>Quality</u> <u>Max Quantity</u> 014807 NECKARZIMMERN River Muddy Unlimited C. <u>Change in status of major equipment.</u> <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Required</u> 2826th E-6 T Prime Mover Bn shop Repairs Inclosures: <u>1</u> Road assignment overlay. 	

0

2

1

4

Acresta



	2400 B Hours	9 April 1945.
Period	Covered: From: 082400	
I.	ADMINISTRATION.	
A.		36th Engineer Combat Group
	Coordinates: 01480	
C.	Engineer Personnel Casualtie	<u>s:</u> (KIA) (WIA) (MIA) 2
III.	OPERATIONS.	
А.	Bridge, bypass, or ford cons	truction, repair and maintenance.
	<u>Coord.</u> <u>Vicinity</u> <u>Type</u> 989830 NECKARELZ Floating T	and a second sec
в.	Roads.	
	282/th Engr Bn Maintained as	signed sectors of road. Removed trees and holes and craters from; S284905 to S415-
		S284905, MEREHINGEN to SECHOF to OB -
	WITTSTADT to MEREHINGEN.	
D.		rk.
		les in road at 047635 vic FRANKENBACH.
		BROCKINGEN. Six loads of crushed rock
		g wounded men and supplies across river
		e and exit approach for dukws at 075618.
	2827th Engr Bn made reconn o	f assigned road and found 263d Engrs
		ing road blocks. Also made reconn of
		moved on site at 091530, ^B with material
		th Engr Bn obtaining I-beams from rail
-		power stations at 023848 and 015807.
E.	Disposition of Troops During	
	Unit 2826th Engr C Bn	Task Pard maintenance formunded you
	202001 Engr C Bh	Road maintenance, ferrying wounded ten and supplies across river, preparir
•		entrance and exit approaches for dr. ws.
	2827th Engr C Bn	Construction of bridge and road mainten-
	Loc or mebr o bu	ance.
	2828th Engr C Bn	Bridge maintenance, guarding power
		stations.
IV.		
A.	Water points in operation.	
	Coord. Vicinity 415938 ASSAMSTADT	Source Quality Max Quantity
		RALPH G. GODFREY
		Captain, 36th Engr C Group
		S=3
	1 .	

/ewh

ANDECLASSIFIED

aD

6

0

MANA Dala

ENGINEER SITUATION REPORT

n	11	11	11 11	11	11	15 15	11
11		S	E	CI	RE	T	h
11 _1 	luti	h:					Gp"
			11	App	ri?	19	45"

	100 B		Hours				945.		
Period	Covered:	From:	092400 B		_ To: _	102	2400 B		
I.	ADMINIST	RATION.							
A.			ting:	6th Engi	ieer Jo	mbat G:	roup		
			03.480		Vic	NECI	KARZIMME		
C.	-	r Personnel	Casualtie	s: (1	(IA)	(11)		(MIA)	
	EM					T	(Shrapne	1)	
III.	OPERATIO	NS.				¥ł.			
A.	Bridge,	bypass, or	ford cons	truction	repai	r and	naintena	nce.	
	Coord.	Vicinity	Type		Lgth	01 Lan	es Scomo	Date Con	mp
			imber Trest	and the second se	40:			100830B	
			imber Trost		601	100 B		101330B	
	989830	NECKAREL Z-1	Loating Tr	eadway	2641	40 1		& improv	ing
в.	Roads.						approac	nes.	
7.		Ener Bn ma:	intaining a	nd impro	ving ro	ad str	etch fro	m 003656	vic
	KIRCHHA	USEN to 071	1606 vic HE	ILBRONN.	2828t	h Engr	En cove	ring roa	đ
	with as	phalt mix a	t 034769.	Work com	pleted	101600	B. Repai	ring cul	vert
			HAUSEN. Wo					ng appro	aches
			e at 980820		omplete	d 1006	00B.		
D.			neering Wo		ine for	+	anohar +	a daalaar a	ito
			intaining e ining entra						
			ngr Bn haul						
			bridge sit						
	Prefabr	icating cu	lvert for i	usertion	at 055	717 up	on comp.	of Bail	ey.
E.			oops During	Period.					
		nit				Task			
	2825th	Engr C Bn						t appro: ince, tra	
	282"th	Engr C Bn						at 448868	
	LOC, M	Targa o Dir						lge at 44	
	2823 1	Engr C Bn					tenance.		
									,
								. 1	
						12 .	11	hll	21

Malph Moley RALPH G. GODFREY

Captain, 36th Engr C Group S-3

/ewh

DECLASSIFIED

MANA, Dale

SECRET



C

SECRET

* * * * * *

	SECRET **********
	Auth: CO ZG Ener Cu
	ENGINEER SITUATION REPORT *Init: 6924
	*Date: 12 April 45 *
	* * * * * * * * * * *
	2400 B Hours 11 April 1945.
Period	Covered: From: 102400 B To: 112400 B
-	
	ADMINISTRATION.
A.	Headquarters reporting: <u>36th Engineer Combat Group</u> Coordinates: 014809 Vic NECKARZIMMERN
III.	OPERATIONS.
A.	Bridge, bypass, or ford construction, repair and maintenance.
	Coord, Vicinity Type Leth Cl Lanes & Comp Date Comp
	053718 JAGSTFELD Bailey 90' 40 1 90
	083761-UNTERGRIESHEIM Bailey 100' 30 1 Maintenance
В,	989830 NECKARELZ Floating Tread 264' Maint. & Improving approaches Roads.
Ъ,	2827th Engr Bn maintained road, HOHEBACH 450868 to STACHENHAUSIN 432-
	832 west to SINDELDORF 360846 to CRISPENHOFEN 352813 to WEISSBACH 349-
	792. Removing vehicles from road, filling in bad spots. Road HOHEBACH
	to STACHENHAUSEN, 2 way class A. Road STACHENHAUSEN to SINDELDORF,
	12 class A. SINDELDORF to 343827, 1 way dirt, class B. Road 343827 to WEIMSBACH, 12 Class A. Maintained road and bridge approaches at HOHE-
	BACH 448868. Filled crater in road at 351819, original fill being re-
	moved ans new fill put in. Filled crater in road at 395840 vic EBER-
	STAL.
D.	
	2826th Engr Bn constructing entrance and exit approaches to duky site at 069646 vic NECKARGARTACH. 2828th Engr Bn guarding power stations
	at 023848 and 015807. Two squads patroling vicinity of bridge 053718
	for security of building party.
E,	Disposition of Troops During Period.
	Unit Task
	2825th Engr C Bn Constructing entrance and exit approaches to dukw site, training.
	2827th Engr C Bn Road maintenance.
	2828th Engr C En Construction and maintenance of bridges,
	guards at power stations.
IV.	EQUIPMENT AND SUPPLIES Water points in operation.
А.	Coordinates Vicinity Source Quality Max Quantity
	447867 HOHEBACH Jagst River Clear Unlimited
C.	
	Org. Item Cause Disposition Action Required 2826th E 21 Thum Truck Bn Shop Repairs
	2826th E $2\frac{1}{2}$ T Dump Truck Bn Shop Repairs
	12 1 1 901 1
	laphil Joe etc
	HALPH G. GODFREY
	Captain, 36th Engr C Group
	/ewh S-3



MARA, Da	
FUUN, DA	SECRET ************************************
/	* SECRET *
	ENGINEER SITUATION REPORT *Auth: CO 36 Engr Gp*
	*Init: //// * *Date: 13 April 1945*
01	
	Hours 12 April 1945. Covered: From: 112400 B To: 122400 B
reriou	00vered. From. <u>112400 B</u> 10; <u>122400 B</u>
	ADMINISTRATION.
A.	Headquarters reporting: 36th Engineer Combat Croup
	Coordinates: 014809 Vic NECHARZIMMERN
В.	Changes in status or location of Battalions or companies: 2827th Engr Bn: Bn Hqs moved to 450867 vic HOHEBACH, "B" Co. moved to
	352812 vic CRISPENHOFEN.
C.	
	EM 1 (S/A)
	AD TO LO
III.	OPERATIONS. Bridge, bypass, of ford construction, repair and maintenance.
	Coord.VicinityTypeLath Cl Lanes % Comp.Date Comp.053718JAGSTFELDBailey90' 40 1 100
	083761 UNTERGRIESHEIM Bailey 100' 30 1 Maintenance
	989830 NECKARELZ-Floating Tread 264' Maint. & improving approaches
В.	
	2828th Engr Bn building culvert at 055717,100% complete. Leveling off culvert site at 053719.
D.	
	2826th Engr Bn maintaining and improving entrance and exit approaches
	to dukw site at 069646 vic NECKARGARTACH. Maintaining ferry site and
	approach roads and operating infantry support raft at site 078616 vic HEILBRONN. <u>2827th Ingr Bn</u> maintained bridge and bridge approaches at
	448868 vic HOHEBACH. Maintained Treadway bridge and bypass at 350792
	WEISSBACH. Reenforcing concrete bridge at FORCHTENBURG 326782. Building
	culvert under Bailey bridge at 352807 CRISPENHOFEN. "C" Co. 2827th
	Engr Bn standing by to build T/D Bailey bridge vic KUNZELSAU. 2828th Engr Bn has one platoon patroling vic of bridge 053718 for security of
	building party. Guarding power stations at 023848 and 015807.
E.	
	Unit Task
	2826th Engr C Bn Maintaining and improving dukw site, main-
	tained ferry site and approach roads & operating infantry support raft, training.
	2827th Engr C Bn Maint. bridge & approaches, standing by to
	build Bailey bridge.
	2828th Engr C Bn Bridge maint., guards on power stations, construction of culverts.
TV.	EQUIPMENT AND SUPPLIES.
	Change in status of major equipment.
	Org. Item Cause Disposition Action Fourid
	2826th E & Ton C&R Ordnance Repairs
	12 Unland
	1 Contraction Contraction
	RALPE G. GCDFREY Captain, 56th Engr C Group
	/ewh



SECRET

			SECR	ET	*	* * * *	* * * * * *	· .
			*		*	SE	CRET *	•
		EN	GINEER SITUA	TION REPOR	RT *A	uth: CO	36 Engr Gp*	
						nit: /7	2.7 1	•
					*I	ate: 14	pril 1945	
					*	* * * *	****	
	400 B	Hour	Construction of the second sec		_ 1945.			
eriod	Covered:	From:	122400 B		To:	13240	ОВ	
-	A THAT COTO A	MTON.						
	ADMINISTRA	ers reportin		The		A		
A.		rdinates:				ECKARZI	ATTON	
в.		n status or		State of the local division of the local div	and the second s			-
2.		2827th Engr					•	
		rori an mil		HEALIO AN	C RONDE	DOBO .		
III.	OPERATIONS		· 2011					
A.		vpass. or fo	rd construct	ton rena	ir and	mainten	ance.	-
	<u>Coord.</u> 074606	Vicinity HEILBRONN H	Type Bonton	Leth C1 240: 40	lanes y		Date Com.	
	014000	HETTORONN H	eavy Foncon			100	131700	manle
	425775	KUNZELSAU	Treadway	601 40			rs in abrve 122300	WOLK.
	423776	Statistics of the statistics of the state of	T Bailey	1701 40	1	10	122300	18 2
	423110		underslung)	10. 40	-	10		
	061717	JAGSTFELD	Overpass	22: 40	2 Ret	nforein	e span	State -
	079709	KOCHENDORF	Timber	341 40	2	75	e oborn	1
	078708	KOCHENDORF	Bailey	110' 40		100	4 m	1
		NTERGRIESHEIN				Intenanc	e	
	989830	NECKARELZ FI					mproving ap	ps.
B	Roads .	2 Alignes	1974		15.1 -0373		The many set	in .
	2826th Er	ngr Bn clears	ng and openi	ng draina	ge dito	ches, ma	intaining a	nd
	improvine	g road strete	h from 00761	O vic GRO	SSGARTA	ACH to C	R at 003640	. Care
		ngr Bn mainta						
		EMSALL 357728						
		ngr Bn clear:						
		Clearing and						
21		il on culver	; at 055/17.	completed	13150) B. Mai	ntaining ro	ad
	020805 to		min o Weals					N
D.		neous Engineo ngr Bn mainta		maurina		a and as	t anorach	de
		site at 0696						
		roads and of						
		N. 2827th En						
		N and 3581 v:						
	and one	at 331775. 14	aintained Tr	estle Trea	adway a	t 350791	vic WIESSB	ACH.
	Construct	ting culvert	under Baile	r at 35280	D7 vic	CRISPENE	IOFFEN. Re-	15
	enforcin	g concrete b:	ridge at 326	782 vic FC	DRCHTEN	BURG by	putting cri	
	under eau	ch arch. Sen	t D-7 to OHR	INGEN to c	lear r	ubble fi	com streets.	新教教 会
		truck sent						
		7 vic CRISPE						and
. 9		es at 448868		1. <u>2828th</u>	1 Engr	Bn guard	ling power	
	stations	at 023848 at	nd 015807.					
					· /		No. State	1
			- 1	• 17. 11.				100 (2)

SECRET



E. Disposition of Troops During Period.

 Unit
 Task

 2826th Engr C Bn
 Maintaining and improving dukw site, maintaining ferry site and approach roads and operating infantry support raft, maintain ing and improving roads, assisted 555th Engrs building heavy ponton bridge 2827th Engr C Bn Relieved bridge guards, maintained coads, maintained bridges and approaches, constructing Bailey bridge at KUNZELSAU. 2828th Engr C Bn Bridge construction and maintenance, guards and road maintenance. 19/16 IV. EQUINENT AND SUPPLITS. A. Water Points in Coeration. CoordinatesVicinitySourceQualityMax Quantity447867HOHEBACHClosed 447867 HOHEBACH Closed 424776 KUNZELSAU River Clear Unlimited C. Change in status of major equipment. Org. Item Cause Disposition Action Required
 2826th E
 2 Ton C&R
 Ordnance
 Repairs

 2826th E
 2 Ton C&R
 Bn Shop
 Repairs
 19.0 Inclosures <u>1</u> Road Overlay olater, account of the state storage Barris - Harry befuilt comments in provinces 551 10 Mits Play and Cost I RALPH G. GODFREY Captain, 36th Engr C Group Vacyared D.S-3 Selly and The south of the sell of the south of the sell The south of the sell of the s /ewh CK 19 TTT ONERE TONT

1 CONTRACTOR MERCH

a12.111111111

10pat 3 cialor 3

and a second sec

water the live site can

We want of the second

· 111 · 首次各国历史。

· FORTER DATE:

SECRET NAMA, Data	* <u>SECRE</u> *
ENGINEER SITUATION	* S E C R * REPORT *Auth: CO 36 Engr Gp*
ENGINEER SITUATION	
	-Init: // -/ 4/ -
	Date: 15 April 1945
2400 B Hours 14 April	1945.
Period Covered: From: <u>132400 B</u>	To: 142400 B
I. ADMINISTRATION.	
A. Headquarters reporting:36th En,	gineer Combat Group
Coordinates: 014809	Vic NECKARZIMMERN
B. Change in status or location of Batta	lions or Companies:
2826th Engr Bn	
"A" Co. moved to 107610 vic HEILBRONN.	"B" Co. moved to 080601 vic
HEILBRONN. 2827th Engr Bn	
"B" Co. moved to 327783 vic FORCHTENER	TRG
II. INFORMATION ON CESTACLES ENCOUNTERED.	and the second se
B. Road Blocks.	
<u>Coordinates</u> <u>Type</u>	Disposition
093621 Abatis	Removed
	and the second
III. OPERATIONS.	
A. Bridge, bypass, or ford construction.	
	h Cl Lanes & Comp. Date Comp.
218727-KOCHERSTEINSFELD-Treadway 132	1 40 1 100 140815B
	1 40 1 Maintenance 1 40 1 100 142400B
061717 JAGSTFELD Overpass 30	40 2 100 141400B
079709 KCCHENDORF Timber 34	40 2 100 141800B
083751 UNTERGRIESHEIM Bailey 100	' 40 1 Maintenance
989830 NECKARELZ Floating Tread264	
	40 1 Maintenance
	140 2 100 142030B
B. <u>Roacs</u> . <u>2826th Engr Bn</u> improving and maintain	
HEILERONN to 058616 vic BROCKINGEN	from 068612 vic HEILBRONN to 074
606 vic HEILBROIN and from 084612 vic	HEILBROIN to 085667 vic NECKARSULA
2827th Engr Bn maintaining road 32878	O vic FORCHTENBURG to 293686 vic
OHRINGEN. Maintaining Trestle Treadwa maintaining bypass at FORCHTENBURG.	y at 350794 vic, WIESSBACH, also
maintaining bypass at FORCHTENBURG.	2828th Engr Bn maintaining road
from 053718 to 079709. Maintaining ro	ad from NECKARELZ 996833 to MUSS-
BACH 035847 to ADELSHEIM 201905 to 08 284905. Inserting culvert at 082691,	acministrat 1)1300B
<u>2826th Engr Bn</u> clearing roads of debu	ris in HEILBRONN. Reconn for engin-
eer material. Maintaining and improvi	ing approaches to bridge site at
074606 vic HEILBRONN. Operating infar	try support raft at 078616 vic
HEILBRONN from 0800 to 1300. Disassen	nbling infantry support raft from
1300 to 1600 and returned it to 325th	h Engrs. Bridge guard at 0/4000 vic
HEILBRONN. 2827th Engr Bn maintained	a approaches to fixed bridge at
448668 vic HOHEBACH. Maintained Trest 2828th Engr Bn guarding power station	ne at 023848 and 015807. Hailing
Bailey bridge parts from bridge to 18	SOLOS VIC WALDURN.
un de la companya de	· · · · · · · · · · · · · · · · · · ·
SECRES	
and the second and a distance is a second of a second and a second and a second and a second a second a second	and a second

. .



a the frenche structure of March (1988) we SECRET

1. 3 4 4

world fair an

Disposition of Troops During Period. E. Unit

NIC RACE PROVIDENCE

The Mercenstration

2826th Engr C Bn Martin Townsin,

Sunday Business

2827th Engr C Bn

2828th Engr C Bn

100 022178 in 013100

CONTRACTOR CONTRACTOR

BUCH ORDERS FO

Trought.

led ba mar

Task - Operating infantry support raft from OSCi. to. 1300, disassembling infantry support . raft, maintaining road stretch, cleared road block in HEILBRONN, recom for engineer material, guarding and maintaining. al a man heavy ponton bridge.

Rama ala

Sale with card

- Constructed Treadway bridge, constructed Bailey bridge, road maintenance. Trestle Treadway and bypasses. Bailey bridge, road maintenance, maintained

- Bridge construction and maintenance, road maintenance, guards at power stations.

Inclosures: 1_ Captured Material Report.

THE CARLESPERT 42 Julian Sector Sector 1, 11 Halle RALPH G. GODFREY Captain, 36th Engr C Group S-3

1934.37

1798)4 CG

Same to de

the inter /ewh

H10.0.30 S055 107 TESSA!

201310

7 1820

Colhin

opi ir!

1.14

And the state of t

ROUND

OLDIFRETUIT . it with 1-3-22.1.14 Constraines a

g. . Harry Stocky Instantion of cruster of constraints 11-1

> and go notor an island a submitted and the SESSET BOUR TO

REFERENCE

NON DO. DEVERSION FOREIO AND HER COLOUR LAN DEPENDENT OF DECKOY LAN Sasacanteach. The

The second s Coord, Millard ALC: TASK w meenstere ------CLANED.

- 2 -

Publica Corevert Promi

and and search the A THEFT

<u>SECRET</u>

公司之后 化 在 二



HEADQUARTERS 36TH ENGINEER COMBAT GROUP APO 758 U. S. Army

15 April 1945

Captured Material Report

German Engineer Dump located at 081663 contained the following:

1000 Chisels, cold length 12" to 36" 1000 Hatchets 1000 Axes 300 Buck Saws 300 Metal Wedges 1000 Saws, Sharpening and setting set 500 31b Hammers 500 8 & 151b Sledges 500 Wooden Mallets 10000 Rolls Barb Wire 5000 Rolls Concertina 3000 Pieces 2" Decking 150 Tons of assorted sizes of Nails and Drift Pins 200 rolls of cyclone wire 200 rolls of chicken wire 1000 rolls of tar paper three-sixteenth inch strap iron, steel fence pickets, fire hose and nozzles.

(Source: 2828th Engr Combat Bn)

DECLASSIFIED.	1-1	SECRET	*****
IIV 7350	··· Kill a state of the second se	GINEER SITUATION REPORT	
and the			*Init: /2 * *Date: 16 April 1945*
And the second s			1945.
Period	Covered: From:	142400 в То	: <u>152400 B</u>
I.	ADMINISTRATION.		and the second se
A.	Construction of the second	:	at Group
	Coordinates:	01.4809 V	ic NECKARZIMMERN
В.	Change in status or loc	cation of Battalions or	Companies:
	2826th Engr Bn Bn Hqs and H&S Co. move 598 vic HEILBRONN. 2827th Engr Bn	ed to 082588 vic HEILBR	ONN. "C" Co. moved to 075-
4.01	"A" Co. moved to 42277		Section of the sectio
C.	Engineer personnel cast	ualties: (KIA)	(WIA) (MIA) 1
II.	OBSTACLES ENCOUNTERED.		
в.	Road Blocks.		
	Coordinates 133625 (WEINSBERG)	<u>Type</u> Abatis	<u>Disposition</u> Removed
III.	OPERATIONS.		
A.		construction, repair a	nd maintenance.
	Coord. Vicinity		s % Comp. Date Comp.
	156627 ELLHOFEN	Culvert 24' 2	100 151600B
		Converted to t	
11	989830 NECKARELZ Float	Bailey 100' 40 1 ing Tread 264' 40 1	Maint. & improving apps. Relieved 150700B.
	078708 KOCHENDORF 156721 NEUNSTADT	Bailey 110' 40 1- Timber 37' 40 2	Maint. Relieved 150700B.
В.	Roads.	a product and the second of the second s	
	stretch from 090620 vi	c HEILBRONN east to 156	ng and improving road 5621 vic ELLHOFEN. Checking 16 to 286684 vic OHRINGEN.
	2827th Engr Bn maintai	ned road MERCHINGEN to	WIESSBACH, class A route
	12 lanes. Maintained r	oad 450867 to 421778 to	409789 to 353813 to 351
		; in pot holes, craters,	
	ditches. Maintained ro	ad 328 (80 Vic FORCHTELL	BURG to 293686 vic OHRINGEN. emoving abatis at 084666.
		nd evacuation roadway f	
8355	056684. Clearing read		
1000	Misce Maneous Ingineer	ing Work.	and the state of the state of the
D,	2826 A Engr Bn clearin	g debris and widening i	street for two way traffic
D,		A Maintaintain annus	and and cardinate have a the
D,	at 133625 vic WEINSBER 07406 vic HEINBROWN	G. Maintaining approach Checking buildings for	VI Coros for mines and .
μ,	074006 vie HEILBROILI.	Checking buildings for	vi Corps for mines and . <u>Engr Bn</u> moved 60° of Bailey
ξŪ,	074606 vic HEILBROHL. booby traps at 286684 bridge from CRISPE HCF	Checking buildings for vic OHRINGEN. <u>2827th</u> I TEN to MOSSBACH. Maintai	VI Corps for mines and . <u>Engr Bn</u> moved 60° of Bailey ined approaches and Tread-
رل ر 	074606 vic HEILBROHL booby traps at 286684 bridge from CRISPE HCE way bridge at KOCHIRSI	Checking buildings for vic OHRINGEN. <u>2827th T</u> TEN to MOSSBACH. Maintan TEINSFELD, Maintained fi	VI Corps for mines and , Engr Bn moved 60° of Bailey ined approaches and Tread- ixed bridge at HOHTBACH.
,D,	074606 vic HEILBROHN. booby traps at 286684 bridge from CRISPE HCE way bridge at KOCHERST Maintained approaches	Checking buildings for vic OHRINGEN. <u>2827th</u> TEN to MOSSBACH. Maintain TEINSFELD, Maintained fi and Bailey bridge at B	VI Corps for mines and <u>Ener Bn</u> moved 60° of Bailey ined approaches and Tread- ixed bridge at HOHTBACH. IRINGEN. Removed Treadway
پ ل ۲	074606 vic HEILBROHN. booby traps at 286684 bridge from CRISPE HCF way bridge at KOCHIRSI Maintained approaches at 425775, brockways r	Checking buildings for vic OHRINGEN. <u>2827th T</u> TEN to MOSSBACH. Maintain TEINSFELD, Maintained fi and Bailey bridge at Bl returned to their unit.	VI Corps for mines and <u>Ener Bn</u> moved 60° of Bailey ined approaches and Tread- ixed bridge at HOHTBACH. IRINGEN. Removed Treadway Policed up bridge site at
"D ,	074606 vie HEILBROHN. booby traps at 286684 bridge from CRISPE HCE way bridge at KOCHERSI Maintained approaches at 425775, brockways r	Checking buildings for vic OHRINGEN. <u>2827th T</u> TEN to MOSSBACH. Maintain TEINSFELD, Maintained fi and Bailey bridge at Bi returned to their unit. -1-	VI Corps for mines and <u>Ener Bn</u> moved 60° of Balley ined approaches and Tread- ixed bridge at HOHTBACH. IRINGEN. Removed Treadway Policed up bridge site at.
j));	074606 vic HEILBROHN. booby traps at 286684 bridge from CRISPE HCF way bridge at KOCHIRSI Maintained approaches at 425775, brockways r	Checking buildings for vic OHRINGEN. <u>2827th T</u> TEN to MOSSBACH. Maintain TEINSFELD, Maintained fi and Bailey bridge at Bi returned to their unit. -1-	VI Corps for mines and <u>Ener Bn</u> moved 60° of Bailey ined approaches and Tread- ixed bridge at HOHTBACH. IRINGEN. Removed Treadway Policed up bridge site at



SECRET 120 1828 in the Miscellaneous Engineering Work (Cont'd) D. 423776 of extra bridge and returned same to 488th Engrs at MOSSBACH. Maintained Trestle Treadway at 350794 vic JIESS BACH. Maintained bypass at F _ CHTENBURG. 2828th Engr Bn Guarding German Engineer Dump at 084-657. Guarding Bailey bridge at 053718 and bridge at 087671. Guarding power stations at 023848 and 015807 State ? E.

and suppry

Disposition of Troops During Period. <u>Unit</u> 2826th Engr C Bn - Checking buildings for mines and booby trap checking and clearing roads for minos, maintaining road, clearing debris, building A Constille culvert, bridge maintenance, and bridge guas 2827th Engr C Bn - Road Maintenance, maintaining trestle tread-way and bypasses, picking up bridge and re-

turning same to proper unit. clearance and construction, guards, EQUIPMENT AND SUPPLIES.

II. C.

Strain and 40 G1224 6

Change in status of major equipment. Org. Item Cause Disposition Action Required <u>Org.</u> <u>Item</u> <u>Cause</u> <u>Disposition</u> <u>Action Redu</u> 2828th E 3/4 Ton C&R <u>35</u>44th Ord. Salvage Inclosures: <u>1</u> Engineer Matorial Report.

<u>SÉCRET</u>

The state of the second states and the second states and the second states and

. 3

the production of the second states and

RAZPH G. GODFREY Captain, 36th Engr C group 1 S-3



HEADQUARTERS 36TH ENGINEER COMBAT GROUP A.P.O. 758

15 April 1945

1, 135.7

ENGINEER MATERIAL REPORT

Map Reference: Town Plan of HEILBRONN, 1:7,000

1....

14

Grid Coord.

M-5

17:

1-4

J-4

Material Fence wire, large mesh, 11 rolls, 15' long. 20 loads washed gravel. Timbers, 12" x 12" x 15' - Boards 1" x 5" x 15!, 1 stack 10' high. 81 wido. Stacked red brick. Timbers: Size 5" x 5" longest 20' 4" x 4" Shortest 6! 3" x 3" 11 Total 50 4" x 5" 11 B#+X*6#1 11

Wert whit w

Washed gravel (not less than 15 loads)

16 "I" beams - 52" with 2 3/4 flange, 30' length 7 pipes, iron -14" diameter, 20' length Other iron pipe in variety of sizes Sheet Iron Iron doweling 15 floor planks 2" x 8" x 15' 12 "I" beams 9" heigth - 4" flange - 15' length. -Sec.

Other "I" beams, miscellaneous sizes.

1[±] x 8" x 15!

Other miscellaneous sizes.

Large supply of gravel and crushed rock. Terval Timbers: 36 - 152" x 101 Longest 401. 20 - 135" x 13" Shortest 20' 15 - 115" x 11" " 1. 1. 3% Others: $5\frac{1}{2^{n}} \times 5\frac{1}{2^{n}} \times 20^{1}$ $7\frac{1}{2^{n}} \times 7\frac{1}{2^{n}} \times 20^{1}$ Flooring: $2^{n} \times 10^{n} \times 15^{1}$

H-4 K-4

M-3

25 rolls, 12 gauge wire. Grillage Lumber, assorted 60 poles, 40' dong, diameter 9" at butt Large number of concrete slabs 2" x 22" x 40" 50 timbers, 20" x 20" x 15'

DECLASSIFIED	
Grid Goord.	Ma uora de
M-4	Timbers: Railroad ties 8" x 9" x 81 - 800
M-4	Timbers: $40 - 4\frac{1}{5}$ x $5\frac{1}{5}$ x 36^{1}
	$\begin{array}{rrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrrr$
N-4.	Flooring: $70 - 2^{"} \times 11^{"} \times 18^{"}$
151	Large Stone pile 10 Timbors $8\frac{1}{5}$ x 15^{3} x 30^{1} (in factory) 60 Planks $2\frac{1}{5}$ x 8^{3} x 16^{7} (in factory)
R-4	"I" besma, menysizes Timbors Flooring.
H-5	"I" beams: 4 - 9 ¹ / ₂ 2 x 10" flange, 5' long 600- 10" x15" flange, 50' long 10 - Chain hoists Timbers Rivets, nuts, bolts, many sizes Portable cement mixers Hand Winches
	Stock Shed: Ropes, Carpenter tools, Drills, Machine parts, Nails (up to 60 d) Jack hammers
G-5	Washedgravel
109	"I" beams: 18", 6 3/4" flange, 25' long
J-5	Flooring: 2", various widths and lengths Posts 3" to 8" in diameter, 8' average length
12- 1	Iron pipes, $10\frac{1}{2}$ diameter, 20' long, other sizes
106	Timbers: $4\frac{1}{2}$, x9" x 13' "I" beams: 5" x5 $\frac{1}{2}$ " x 30'
Sale - 1	18 - 7" x 7" x 30' 10 - 5章 x 5章" x 35' 12 - 7" x 3章" x 25'
9919 G287 (*	$2 - 7'' \times 7'' \times 35''$ 12 - $8\frac{1}{2}'' \times 4'' \times 48'$
es regaraudas (soc	Cement: 30 bags Stock Rooms; Wrenches, Files, Brushes, Nails, Vire Brushes, Glèves, Nuts, bolts, Rivets and Welding Rods.
N-7	Gravel, Crushed Rock
Center P-Q -6	Gravel

- - xin to

and the second s

0

JACOOL	CLASSI	IFO:	1245
	1725	n/	2
Aboilty	. :		23
BAR	MANA,	Dato	
- age	and		TAS.

<u>S E C R E T</u> Auth: CO 36 Engr Gp Init: Date: 17 April 1945

2400			Jours16 April	1945		
Period	Covered:	From:	152400B	To::	162400 B	
I.	ADMINISTH	ATION.				
A.	Headquar	ters repor	nting: 36th 014809	Engineer Con	Dat Group	
В.	Changes	in status	or location of	of Battalions	or Companies:	· 708
	2826th H	ingr Bn				
			180610 vic WI	LLSBACH		
	2827th H	moved to	+23775 vic KUN	TZELSATT		
la stand	2828th H			CELLORO .		
	vic OHRI	H&S Co. INGEN. "B' 2 vic EMM	" Co. moved t	587 vic OHRIN 331784 vic	IGEN. "A" Co. moved FORCHTENBURG. "C'	1 to 286679 ' CO.moved
II. 3	INFORMATIC	ON ON OBST	ACLES ENCOUNTE	ERED.		
		neous obs				
(1)	(handdar				D	
y	Coordina 104626	ites	5 Teller M	line #2 I	Disposition Removed and Destro	ved
	136636				Removed and Destro	
	Bridge		ford construct	tion renair	and maintenance.	
	the suggest	MUMPS, VI	1010 0040010	VAUNA LOUMAA	CHARLE MILLING CARCING CO	
	Coord.	Vicinit		Leth Cl La	ies % Comp. Date	
	347791	WEINSBER		1321 40 1	90 17100 Maintenance	0, B
	156821	NEUNSTAD		37" 40 2		·
	Roads.				A.	
1	2826th En	r Bn fill	ing holes, re	emoving debr	ts, and maintaini vic ELIHOFEN, from	ng road
					of local material	
1	dumpeate Of	1612 vic	HEILBRONN, on	above jobs.	Cleared roads of	enemy
					through HOLZERN?	
					th Engr Bn maintai to 352815 to 29584	
					ge ditches. Nainta	
	road from	WIDDERN 2	25810 to OHRI	NGEN 285685	, also road from W	IDDERN
	225810 to	BUCHSEN 1	95812, roads :	require cont	inual maintenance.	2828th
			eering Work	0 422 (15 to	414702 to 285685.	
	2826th En	gr Bn clea	ring streets	of debris an	d enemy vehicles a	t 136633
					nd grenadesatt 091	
1	noved and	destroyed.). Filled cra	ter at 15362	4 vic ELLHOFEN. M HEILBRONN, reliev	aintained ed of
	approache assignmen	t at 16120	OB. Checked ad	iditional bu	ildings for mines	and booby
	traps for	VI Corps	CP, work compl	Leted. 2827	rh Engr Bn hauling	decking
			-1-		P. S. S.	
		S	ECRET	· · ·		
						- 1



SECRET

D.	Miscellaneous Engineer:	ing Work (Contid)
	io MOSSBACH. Packed up	German explosives in KUNZELSAU and disposed of
- 1	same. Filled holes in a	pproaches to bridge in WIDDERN.A2828th Engr Bn
		for fixed bridge at 423683. Building duck boards
	and showers for 92nd De	econtamination Gas Company.
E.	Disposition of Troops 1	Juring Period.
	Unit	Task
	2826th EngrC Bn	- Clearing streets of enemy vehicles and
		debris, road maintenance, policing and
		destroying enemy equipment, checking
		buildings for mines for VI Corps CP, sup-
		porting 100th Inf Div, maintaining approaches
		and guarding bridge.
	2827th Engr O Bn	- Road maintenance, hauling decking to MOSS-
		BACH, moved to a new location, supporting
		63rd Inf Div.
95	2828th Engr C Bn	- Bridge construction and maintenance, read
		maintenance, moving to nrw location, sup-
		porting 10th Armd. Div.

RALPH G. GODFREY Captain, 36th Engr C'Group S - 3

SECRET

- 2 -



(

			SECRE	<u>r</u>	* * * <u>S</u> * <u>E</u> * <u>C</u> * <u>R</u> * <u>E</u> * <u>T</u> *	* *
		TIG	INEER SITUATION	N REPORT	*Auth: CO 36 Engr	• Gp*
				•	*Date: 18 April 1	945*
	2400 B		s17 Apr	<u>il</u>	_ 1945.	
Period	Covered: Fr	rom: <u>16</u>	2400 в	'l'o:	172400 B	019°, .
Ι.	ADMINISTRATI	ON.				
A.	Headquarter	rs reporting:	<u>36th En</u> ,	cineer Com	Dat Group	1 19 19 19
		linates:	313689	Vic	SCLAFDTSWEILER	
В.	Group Hqs.	moved to 313	ation of Batta 689 vic BULARD	ISWEILER.	ompalies:	
II. B.	Road Blocks		ENCOUNTERED.		1	
D.	Coordinates	Pero un	Type		Disposition	
	389676	-	Crater		Filled	Sec. Sec.
	380650		Abatis	Chine States	Removed	112
III.	OPERATIONS.		- to a way to	, 1963 (full all) Territor sub-	GONGE CARGONICATION AND A	141
A.	Bearing and and a second state of the second s	bass, or ford	construction,	repair and	1 maintenence.	(2]题: -
	Coord. N	<i>licinity</i>	Type Lgt	h Cl Lanes	% Comp. Date Con	m.
	483709 DC		Ford		100 172400B	1. (T)-
		ESTERNACH EISBACH	Timber 20 Treadway	40 2	100 172000B Maintenance	1
В.		11 CLOROII	TICAUMAY	-+U I	Mainvenance	1758 (1
31 2	.2826th Engi road strete	ch from 13362	5 vic WEINSBER	G east to a	ruble, and maintai 249679 vic BITZFEI	D east
					NN north to 081661	
					to 135553 vic HAPP n 181609 vic WILLS	
14	southeast t	to 223562 vic	HIRRWEILER. A	pproximate.	ly 30 loads of roc	k and.
and there					oulders for mines	
	detail 50%	completed -	no mines found	2827th	WEINSBERG. Sweepi Engr Bn maintained	road
	from OHRING	JEN thru KOCH	ERSTRINSFELD n	orth to BI	ERINGEN, and from	OHRINGE
	on 10th Arm	nd Div LISR to	WESTENHAUSEN.	Maintaine	d roads from 29168 finished partial	5 to
	craters alo	ng road from	430770 KUNZEL	SAU to 483	709 DOTTINGEN. 28	328th
	Engr Bn cle	earing roads	between HEUBER	G 285637 t	o GLEICHEN 305611	to
					g shell crater in	
	faced homb	crater at 41	4759. Improvin	e and main	n culvert at 4266 taining road at 38	39676 fc
1	two way tra	affic, wideni	ng road to two		0650, and widening	
х.+	ATT HALDEND	JRG for two w	ay maine.			
			- 1 -	And a second sec		-
				3		
			SECRE	T		1

1

an in

SECRET



1. -



176:31

	ENGINEER SITUATION REPORT * SECRET *Auth: CO 36 Engr Gp* *Init: \checkmark 2. \checkmark 2.
	Date: 19 April 1945

Period	2400 B Hours 18 April 1945. Covered: From: 172400 B To: 182400 B
I.	ADMINISTRATION.
A.	
	Coordinates:
B.	Change in status or location of Battalions or Companies:
	282Eth Engr Bn
	Bn Eqs and H&S Co. moved to 420571 vic MICHELFELD. "A" Co. moved to 330- 547 vic MAINHARDT. "C" Co. moved to 432616 vic WACKERSHOFEN.
III.	OPERAL DYS.
A.	Bridg, bypass, or ford construction, repair and maintenance.
e.	Coord. Vicinity Type Lgth Cl Lanes 5 Comp. Date Comp.
7.4-	120558 UNT-GRUPPENBACH Timber 25! 40 2 10 190600B
	458633 UNT-MUNKHEIM Floating Tread 96' 40 1 100 180630B
	485708 DOTTINGEN Ford 1 Maintenance 448643 UNT-MUNKHEIM Culvert 40' 2 100 181500B
	458634 UNT-MUNKHEIM Timber Trestle 40! 40 2 25 192330B
В.	new a transmitt key an at a part where a set is the set of the set
1.	<u>Roads</u> : <u>2826th Engr Bn</u> maintaining and improving road stretch from 182605 vic
	WILLSBACH south to 200561 vic LOWENSTEIN then east to 375555 vic BUBEN-
S. S. Frank	CRBIS. Filling craters in road from 140551 vic HAPPENBACH east to 158552
	vic UNTER HEINRIET. Sweeping shoulders of roads for mines from 175656
	vic HOLZERN east to 280686 vic OHRINGEN. From 157621 vic ELLHOFEN south to 160551 vic UNTER HEINRIET, and from 182605 vic WILLSBACH south to
	200561 vic LOWENSTEIN east to 375555 vic BUBENORBIS. Completed sweeping
E.	shoulders of roads for mines from 117604 RJ to 117572 vic DONNBRONN to
	127625 vic WEINSBERG. No mines located. 2828th Engr Bn.cleared mines
	to ditches from GLEICHENUNT 615305 to 578335 vic of GERSSILHARDT. Re-
	moved abatis from coordinates 630295, 620302, 630320, and 330595 vic
	FRONN FALLS. Cleared roads of mines and debris for two way traffic from UNTERHOFEN 310646 to UNTSTEIBACH 337620. Removed 2 improvised AT mines
	and 6 Schu mines. Removed charges from bridge at HENHOLZ. Approximately
	400 lbs of explosives consisting of boosters for Nebelwerfer mortars
	were found on the site. Filling in culvert at .428678. Widening road at
	GAILENKIRCHEN 428628, WACKERSHOFEN 434613 and filling crater and widen-
	ing road at GOFTWCLLSHAUSEN 445602 to take two way traffic. Sweeping
	shoulders of road 442583 to 440570 for mines. No mines found. Removing road block at 397567.
	TORU OTON AU JJ[J0].

* .

12

SECRET

-1-

いまでの「単位の」という目的のと、自動理論を可能のです。 いいかいい

D. Miscellaneous Engineering Work. 2826th Engr Bn removing debris from blown ovorpass at 135553 vic U.TER-HEINRIET. Building house trailor for VI Corps Hqs. 2827th Engr Bn filled crater at 463614 vic GELBINGEN, 100% complete to 12 lane traffic. 12 man guard on power plant for VI Corps at 290685 vic OHRINGEN. Maintaining approaches to Bailey bridge at 423776 vic KUNZELSAU and doing genera maintenance on bridge. Haintaining Floating Treadway in vic UNT-HUNKHEIH 458632. Maintaining ford at DOTTINGEN. Removed five 250 lb bombs at 439643. Maintaining Treadway bridge at KCCHERSTEINSFELD. 2828th Engr Bn constructing approaches to bridge at 423682, completed 181800B. E. Disposition of Troops During Period. Unit Task 2825th Engr C Bn - Constructing Fixed bridge, operating check point, training, road maintenance, building trailer for VI Corps. - Constructed culvert, 12 man guard on power 2827th Engr C 3n plant, maintaining Bailey bridge and Ford. 282 in Engr C Bn - Bridge construction, mine clearance, road construction and maintenance. - Checked hospital site of 619th Clearing Co: Hqs, 36th Engr C Gp. for mines, one driver from Hq Co. on T/D with VI Corps. - 14 COLUMPS EQUIPMENT AND SUPPLIES. IV. All previous water points in operation, closed. A. Water Points in Coeration. Coordinates Source Quality Max Quantity Vicinity River Clear Unlimited 424776 KUNZELSAU Clear Unlimited WIESSBACH River 351791 Inclosures: 1 Bridge Reconn Report & Sketch. an and the the alph J Sudfilly RALPH G. GODFREY Captain, 36th Engr C Group 5-3 /ewh

-2-SECREI



ENGINEER SITUATION REPORT

SECRET Auth: CO 36 Engr Gp Init: Date: 20 April 1945

				PDIII 7949
_ 2400	B Hours	19 April	1945	
Contraction of the local division of the loc	Covered: From: 1824		0: 192400 B	
		the second s		
I.	ADMINISTRATION .			
A.	Headquarters reportin	g:: 36th Enginee	r Combat Group	
· · · · · · · · · · · · · · · · · · ·	Coordinates: _ 3		Vic _ ECKARDTSWEI	LER
В,	Change in status or 1			
No and the	2826th Engr Bn:			
	"All Co. moved to 1975	88 vic BRIETENAUER	HOF. "B" Co. moved	to 189585 vic
	HOSSLINSULZ.	1. S.		
	2828th Engr Bn:			
	"A" Co. moved to 4034	40. "B" Co.moved t	0 430450. "C". Co.	moved to 455445.
		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		
III. C	OPERATIONS.		Section Contraction Contraction	
A.	Bridge, bypass, or f	ord construction, r	epair and mainten	ance.
	and the second second second second second		an station of the	La Connect Street
	Coord. Vicinity	Type Leth C	L Lanes %. Comp	Date Comp.
	120558 GRUPPENBACH	Timber 25 40	2 100	190530B
.t.	311531 HOHENGARTEN	Bailey-D/S 70' 40	1 100	191630B
	458634 UNT-MUNKHEIM	Timbertrestle40'40		192400B
		Treadway 60' 40	1 100	192100B
	457595 SCHWABISH HAI	L Conct.T/Slab140"	40 2 35 R	epatr 202400B
В.				
	2826th Engr Bn. filli	ng shell holes, r	emoving debris, m	aintaining and improving
Not the	road stretch from 210	560 vic LOWENSTEIN	south to 215551	RJ southeasto 196-
1.	542 vic ETZLENSWENDEN	. From 215551 RJ	southwest to 2405	26 vic NEULAUTERN. From
				Sweeping shoulders of
	road stretch from 191	656 RJ southeast t	o 200649 vic DIMB	ACH, and from 209658
1				proximately 12 loads of
				2828th Engr Bn sweep-
			467462 and sweepi	ng from 420570 to 455-
	590. Budlt bypass at			
D.	Miscellaneous Engine			
	2827th Engr Bn 22 man			
				SAU and doing general
				dway in vic of UNT-MUNKHEIM
				ance of Treadway KOCHER
				timbers and decking, and
1997	standing by in suppor		at team.	
E.	Disposition of Troops	During Period.	Me ala	
	Unit.	Deed meintenense	Task	nation had the
	2826th Engr C Bn	Road maintenance		
	000741 To			ting 100th Inf Div.
	2827th Engr C Bn	Constructing timb		
	*	and maintenance o		4th and 63rd Divs.
a de la companya de	Sooth Ener C Br			md Div, in process
	2828th Engr C Bn	of moving.	apporting toon wi	me nra, ru biocess
		or moving.		
		-1-		The state of the second state of the second s
		- T -		

SECRET



A.

SECREE

IV. EQUIPMENT AND SUPPLIES. C. Change in status of major equipment.

Org. 2828thE	Item Dump Truck,	<u>Cause</u> Broken Dump	Dispo 3544th	sition Ord.	Action Required Repair
2828th I	Prime Remo	over, Burnt ou			
Water Po	oints in ope	eration.			
Coordina	tes Vie	cinity S	ource	Quality	Max Quantity
424776	KUNZEI	LSAU Riv	er	Clear	Unlimited
457595	SCHWABISH	HALL Riv	ver	Clear	Unlimited

RALPH G. GODFREY Captain, 36th Engr C Group S - 3



.

4

			SECR	ET	* * * * * *	* * * * *
		TITOTI			* $\underline{S} \underline{E} \underline{C}$ *Auth: CO	<u>RET</u> *
		ENGI	NEER SITUATI	ON REPORT	*Auth: CO	36 Engr Gp*
					*Init;	
					"Date: 21 A	pril 1945*
	2400 B	Hours	20 Apri	1	1945.	
			2400 B	To:	202400	'B
				THE PROPERTY OF		
I.	and a state of the second s	-Conditional and a second second				
A.		ers reporting				the second s
		dinates:			OBERROT	
В.	Change in 2826th Eng	status or loc r Bn	cation of Ba	ttalions or	<u>Companies</u> :	
	Bn Hqs and	H&S Co. move	ed to 274574	vic NEUHUI	TEN. "A" Co.	moved to 300-
	560 vic AM 2827th Eng	ERTSWEILER.	"C" Co. move	d to 300558	vic AMERTSV	TEILER.:
			vic LORCH.	"B" Co. mov	red to 393321	vic WELZHEIM.
		ved to 45858!	5 vic SCHWAB	ISH HALL.		•
	2828th Eng		1. 1. V			
	"A" Co. mo 240.	ved to 43124	0. "B" Co. n	loved to 431	1451. "C" Co.	moved to 430-
	Group Has,	36th Engr C	Group		• •	
	Group Hqs	moved to 410	479 vic OBER	ROT.		
III.	OPERATIONS.					
A.		mass, or for	d constructi	on, repair	and mainten;	ance.
	Coord.	Vicinity	The second se	A CARE AND A	nos S Comp.	
	311531 HC	HENGARTEN	Timber	501 40	2 20	221200B
	457595-SCF	WABISH HALL-	Concrete T/S	1ab-1401-40)-2 100	202400B_Repair
В.						
						shoulders of
						to 350440 vic
	from 20016	Kemoving de	Oris and wid	(ening ior)	wo way train	ic road stretch 2827th Engr
						BERG 427409,
						RCHEMBERG 427-
	409 to LOF	RCH 430240, t	his road als	the 10th	Armd Div MSI	R. Maintaining
•	cordoroy a	coad from 460	500 to 46052	0. 2828th	Engr Bn clea	aring road for
	two way to	raffic in vic	of WASCHENE	EUREN 4351	5. Clearing	road blocks
		ing for mines				- <u>-</u>
D.		ous Engineer		Section 1 - Fort	the second and	dit in the
						7727. Maintain-
		ing treadway			its . ray	
E.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	on of Troops	During Peric	od.		
27.	2826th Eng	<u>lit</u> The Dra	Pood	maintanana	Task	ing timner brid
	LOCOUL MIE	51 1011				for VI Corps,
						atoons of "B"
					of 117th Rec	
	2827th Eng	gr Bn		and bridge		supporting
	2828th Eng	gr Bn		orting 10th	Armd Div.	
			- 1 -	and the second		. ⁽⁶⁾
			SECR	ET		



. . .

<u>SECRET</u> <u><u>Source</u><u>Quality</u><u>MaxQuantity</u></u> IV. EQUIJ ENT AND SUPPLIES. A. Water Points in Operation. CoordinatesVicinity424776KUNZELSAU457595SCHWABISH HALL Closed. River Clear Unlimited 457595 SCHWABISH HALL River Clear Unlimited RALPH.G. GCDFREY Captain, 36th Engr C Group S-3 ten en gan en anter Agrommente The data with the second Nation Branch Constant Restance (Constant Andrew Constant Andr Technic Contraction
 Society
 Standard Sector
 Standar LA CARDENSE Ne Constantin and a state - 2 ----- (n.) SECRET STATE AND ADDRESS AND ADDRESS 1
AINDO	ECLASSIFIED	
Authority	735011	
And	MANIA, Dala	
CHURY.	NATA DATA	

		<u>secret</u> . <u>secr</u>
	1	
		ENGINEER SITUATION REPORT :Auth: CO 36 Engr :Init: K. 4.1.
		:Date: 22 April 194
	. 240	0 B Hours 21 April 1945. Govered: From: 202400 B To: 212400 B
P	eriod	
		ADMINISTRATION
	A.	Headquarters reporting: 36th Engineer Combat Group
	в.	Coordinates: 436235 Vic LORCH Change in status or location of Battalions or Companies:
		2826th Engr Bn: Bn Has & H&S Co. moved to 242405 vic
		BACKNANG. "A" Co. moved to 242406 vic BACKNANG. "B" Co. moved to 215325 vic WINNENDEN. "C" Co. moved to 261'44
		moved to 215325 vic WINNENDEN. "C" Co. moved to 261144 vic OPPENWEILER. 2827th Engr Bn: Bn Hqs moved to 442239.
	(R)**	vic LORCH. "A" Co. moved to 410155 vic BARTEN BACH. "B"
	•	Co. moved to 443239 vic LORCH. 2828th Engr Bn: Bn Hqs &
		H&S Co. moved to 403141. "A" Co. moved to 268068. "B" Co.
•	a	mo d to 429239. "C" Co. moved to 259071.
	0.	Engineer Personnel Casualties: (KIA) (WIA) (MIA)
	· · · · · ·	
• *	II.	INFORMATION ON OBSTACLES ENCOUNTERED.
	: B.	Road Blocks.
		L27525 Abatis Bemoved
. 14		424449 Log Barricade Removed
		443272 Timber Fost Upright Open to 2 way traffic
	· D.	
	D.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD.
	D.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTEI
•••	D.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTEI Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of
••	D.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first
	D.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTEI Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici-
•	D.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTEI Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the
	D.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTEI Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici-
•		Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap.
	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap.
	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap.
	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap. <u>OPERATIONS:</u> <u>Bridge, bypass, or ford construction, repair & maintenance</u> Coord. Vicinity. Type Ligth Cl Lanes %Comp Dute Co
•	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap. <u>OPERATIONS:</u> <u>Bridge, bypass, or ford construction, repair & maintenance</u> Coord. Vicinity. Type Ligth Cl Lanes %Comp Dute Co
•••••••••••••••••••••••••••••••••••••••	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap. <u>OPERATIONS:</u> <u>Bridge, bypass, or ford construction, repair & maintenance Coord. Vicinity Type Ligth Cl Lanes %Comp D te Co 312531 HOHENGARTEN Timber 50' 40 2 60 221800B :238397. BACKNANG Bailey T/S 100' 40 1 100 210130B 272457 SULZBACH Reinforcing to Class 40</u>
•••••	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap. <u>OPERATIONS:</u> <u>Bridge, bypass, or ford construction, repair & maintenance Coord. Vicinity Type Ligth Cl Lanes %Comp D te Co 312531 HOHENGARTEN Timber 50' 40 2 60 221800B :238397. BACKNANG Bailey T/S 100' 40 1 100 210130B 272457 SULZBACH Reinforcing to Class 40</u>
••••	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap. <u>OPERATIONS:</u> <u>Bridge, bypass, or ford construction, repair & maintenance Coord. Vicinity Type Ligth Cl Lanes %Comp D te Co 312531 HOHENGARTEN Timber 50' 40 2 60 221800B :238397. BACKNANG Bailey T/S 100' 40 1 100 210130B 272457 SULZBACH Reinforcing to Class 40</u>
••••	III.	Removed and destroyed 5 Topf mines at 102532 vic ILSFELD. Removed & neutralized 4 Schumines at 127525 vic AUENSTET Road bridge at SWABISCH GMUND.vic 519248 had concrete floo ing removed. The two center steel stringers of a total of six, had a wedge-shape cut in them, not apparent at first inspection. New flooring material was hidden in the vici- nity. It was obvious that the enemy intended to redeck the bridge and use it as a tank trap. <u>OPERATIONS:</u> <u>Bridge, bypass, or ford construction, repair & maintenance</u> Coord. Vicinity. Type Ligth Cl Lanes %Comp Dute Co

.....

MANA, Data

B. . Roads. --2826th Engr Bn filling holes and maintaining road stretc' from 286465 vic SULZBACH south to 241408 vic BACKNANG, and from 286465 vic SULZBACH northeast to 250500 vic SPE-IGELBERG. 2827th Engr Bn maintaining roads from SCHAB-ISH HALL 456590 to KIRCHENKIRNBERG 427408; filling rot and shell holes, and checking relief and drainage ditches Maintaining MSR from LORCH thru BRUCK 444262, BRECH, WELZ Hilm, to KIRCHENKIRNBERG; clearing road to full 2 way traffic and building up soft shoulders from 440407 to 451406. 2828th Engr Bn clearing debris from road at 410-155, completed 211800B. Removed road block and filled 3 1 crater at 458235, completed 211800B. D. Miscellancous Engineering Work 2826th Engr Bn repairing culvert at 259482 vic BERNHALDEN Filling craters at 254490 vic SPEIGEBBURG, 102532 vic ILSFELD, 130553 vic HAPPENBACH. 18 loads of rock used on above jobs. 2827th Engr Bn checked bridge at LORCH 444-238 for demolitions, none found. Working on airport vic GOPPINGEN 447138. 2828th Engr Bn removed demolition from bridge at 493232. Demolition consisted of 4 500 kg bombs. Disposition of Troops During Period. Unit Task 2826th Engr Bn - Constructing Bailey bridge, builting house trailer for VI Corps, filling craters & lifting mines filling craters & lifting mines & 1. removing abatis, supporting 100th an same and Div. 282.7th Engr Bn - Bridge & road maintenance, moving, working on airport, supporting 44th Div. 2828th Engr Bn - Road clearance, removal of demolitions, moving, supporting 10th Armd Div. IV. EQUIPMENT AND SUPPLIES. Disposition Action Pag. Bn Repair Repairs Repairs 2827 E 242 T Truck valve bell Ordnance

2 -

Ralph M. Had frey

Repairs

1

RALPH G. GODEREY Captain, 36th Engr C Group S-3

/ewh



ENGINEER SITUATION REPORT .

<u>SECRE</u> Auth: CO 36 Engr Gp Init: Date: 23 April 1945

0	Covered: From: 2124	22 April 1945	2224008
			<u></u>
I.			
A.	Headquarters reporting:		
_	Coordinates:436		
Be	Change in status or locat	ion of Battalions or	Companies:
	2826th Engr Bn: Bn hqs mo	oved to 220321 vic WIN	NEDEN. 2827th Engr Bn; Bn hqs
1	moved to 267070 vic KIRCH	HEIM. "B" Co. moved t	o 255065 vic KIRCHHEIM. "C"Co.
	moved to 267068 vic KIRCH	HEIM.	
TT	TNEODMANTON ON ODGMACIES IN	COULTERED	
	INFORMATION ON OBSTACLES EN	COUNTERED.	
D.	Road Blocks.		
	Coordinates	Type	Disposition
	275160	Abatis	Clearing
	288082-269072	Abatis	Removed
TT.	OPERATIONS.		
D.		Work.	
_			g strip 100' X 3000" at airpott
	vic GOPPINONN-Field is cof		
			landed. 2828th Engr Bn checking
	VI Corps bivouac area for		
		mines and boony trabs	. WOIK COMDIELEG CCLOUD.
A.			
A.	Bridges , bypasses, or ford	constructions. repai	r and maintenance.
A.	Bridges . bypasses. or ford Coord: Vicinity	constructions, repair	r and maintenance. clLanes %Comp_Date Comp.
A .	Bridges , bypasses, or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1	t constructions, repair Type Leth Loating Tread 96	r and maintenance. cl Lanes %Comp Date Comp. 40 1 Removed
	Bridges , bypasses, or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD	t constructions, repair <u>Type</u> Leth Loating Tread 96' Treadway 132'	r and maintenance. cl Lanes %Comp Date Comp. 40 1 Removed
A. E.	Bridges bypasses or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri	t constructions, repair <u>Type</u> Leth Loating Tread 96' Treadway 132'	r and maintenance. cl Lanes %Comp Date Comp. 40 1 Removed
	Bridges bypasses or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri Unit	<u>I constructions, repai</u> <u>Type Leth</u> loating Tread 96' Treadway 132' ing Period. <u>Task</u>	r and maintenance. c <u>l Lanes %Comp Date Comp</u> . 40 1 Removed 40 1 Removed
	Bridges bypasses or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri	i constructions, repai <u>Type Leth</u> loating Tread 96 ¹ Treadway 132 ¹ Ing Period. <u>Task</u> Building House Tread	r and maintenance. cl Lanes Comp Date Comp. 40 1 Removed 40 1 Removed
	Bridges bypasses or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri Unit 2826th Engr C Bn	l constructions, repai <u>Type Leth</u> loating Tread 96 ¹ Treadway 132 ¹ ing Period. <u>Task</u> Building House Tra 100th Inf Div. Con	r and maintenance. cl Lanes Comp Date Comp. 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge.
	Bridges bypasses or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri Unit	l constructions, repai <u>Type Leth</u> loating Tread 96 ¹ Treadway 132 ¹ ing Period. <u>Task</u> Building House Tra 100th Inf Div. Con	r and maintenance. cl Lanes Comp Date Comp. 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, cleari
	Bridges bypasses or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri Unit 2826th Engr C Bn	i constructions, repai <u>Type</u> <u>Leth</u> loating Tread 96 ¹ Treadway 132 ¹ ing Period. <u>Task</u> Building House Tra 100th Inf Div. Con Working atrport, 1 abatis, supporting	r and maintenance. cl Lanes Comp Date Comp. 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, cleari
	Bridges , bypasses, or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri Unit 2826th Engr C Bn 2827th Engr C Bn	i constructions, repai <u>Type</u> <u>Leth</u> loating Tread 96 ¹ Treadway 132 ¹ ing Period. <u>Task</u> Building House Tra 100th Inf Div. Con Working atrport, 1 abatis, supporting	r and maintenance. cl Lanes Comp Date Comp. 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc
	Bridges , bypasses, or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri Unit 2826th Engr C Bn 2827th Engr C Bn	i constructions, repair <u>Type</u> <u>Leth</u> loating Tread 96' Treadway 132' ing Period. <u>Task</u> Building House Tra 100th Inf Div. Con Working atrport, n abatis, supporting Checking VI Corps	r and maintenance. cl Lanes Comp Date Comp. 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc
	Bridges , bypasses, or ford <u>Coord: Vicinity</u> 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD <u>Disposition of Troops Duri</u> <u>Unit</u> 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn 2828th Engr C Bn	i constructions, repai <u>Type</u> <u>Leth</u> loating Tread 96' Treadway 132' <u>Ing Period</u> . <u>Task</u> Building House Tra 100th Inf Div. Cor Working atrport, n abatis, supporting Checking VI Corps supporting the 10t <u>Leth</u> <u>C1</u> Lanes	<u>r and maintenance.</u> <u>cl Lanes Comp Date Comp.</u> 40 I Removed 40 I Removed 40 I Removed attracted Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc ch Armd Div. <u>Comp Date Comp</u> .
	Bridges , bypasses, or ford Coord: Vicinity 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD Disposition of Troops Duri Unit 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn	i constructions, repai <u>Type</u> <u>Leth</u> loating Tread 96' Treadway 132' ing Period. <u>Task</u> Building House Tra 100th Inf Div. Cor Working atroort, n abatis, supporting Checking VI Corps supporting the 10th <u>Leth</u> <u>Cl</u> Lanes	r and maintenance. cl Lanes Comp Date Comp. 40 I Removed 40 I Removed 40 I Removed attracted Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc ch Armd Div.
	Bridges , bypasses, or ford <u>Coord: Vicinity</u> 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD <u>Disposition of Troops Duri</u> <u>Unit</u> 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn 2828th Engr C Bn	i constructions, repai <u>Type</u> <u>Leth</u> loating Tread 96' Treadway 132' <u>Ing Period</u> . <u>Task</u> Building House Tra 100th Inf Div. Cor Working atrport, n abatis, supporting Checking VI Corps supporting the 10t <u>Leth</u> <u>C1</u> Lanes	<u>r and maintenance.</u> <u>cl Lanes Comp Date Comp.</u> 40 I Removed 40 I Removed 40 I Removed attracted Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc ch Armd Div. <u>Comp Date Comp</u> .
	Bridges , bypasses, or ford <u>Coord: Vicinity</u> 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD <u>Disposition of Troops Duri</u> <u>Unit</u> 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn 2828th Engr C Bn	i constructions, repai <u>Type</u> <u>Leth</u> loating Tread 96' Treadway 132' <u>Ing Period</u> . <u>Task</u> Building House Tra 100th Inf Div. Cor Working atrport, n abatis, supporting Checking VI Corps supporting the 10t <u>Leth</u> <u>C1</u> Lanes	<u>r and maintenance.</u> <u>cl Lanes Comp Date Comp.</u> 40 I Removed 40 I Removed 40 I Removed attracted Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc ch Armd Div. <u>Comp Date Comp</u> .
	Bridges , bypasses, or ford <u>Coord: Vicinity</u> 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD <u>Disposition of Troops Duri</u> <u>Unit</u> 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn 2828th Engr C Bn	I constructions. repair Type Leth loating Tread 96' Treadway 132' Ing Period. Task Building House Translow Task Building House Translow Task Building House Translow Tore 100th Inf Div. Cornworking atroopt, respective Tore Checking VI Corps Supporting the lot End Lgth Cl Lanes 50' 40	<u>r and maintenance.</u> <u>cl Lanes & Comp Date Comp.</u> 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc ch Armd Div. <u>& comp Date Comp.</u> 100 222400B
	Bridges , bypasses, or ford <u>Coord: Vicinity</u> 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD <u>Disposition of Troops Duri</u> <u>Unit</u> 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn 2828th Engr C Bn	I constructions. repair Type Leth loating Tread 96' Treadway 132' Ing Period. Building House Translow 100th Inf Div. Corr Working atroort, results, supporting Checking VI Corps supporting the lot 2 Lgth C1 Lanes or 50' 40 2	<u>r and maintenance.</u> <u>cl_Lanes & Comp_Date Comp.</u> 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road bloc ch Armd Div. <u>& comp_Date Comp.</u> 100 222400B
	Bridges , bypasses, or ford <u>Coord: Vicinity</u> 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD <u>Disposition of Troops Duri</u> <u>Unit</u> 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn 2828th Engr C Bn	I constructions, repai <u>Type</u> <u>Leth</u> loating Tread 96 ¹ Treadway 132 ¹ <u>Ing Period</u> . <u>Task</u> Building House Tra 100th Inf Div. Con Working atrport, 1 abatis, supporting Checking VI Corps supporting the 10t <u>E Leth C1 Lanes</u> er 50 ¹ 40 2 REI	r and maintenance. cl Lanes Comp Date Comp. 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road block ch Armd Div. <u>Comp Date Comp.</u> 100 222400B
	Bridges , bypasses, or ford <u>Coord: Vicinity</u> 458633 UNT-MUNKHEIM F1 218727 KOCHERSTEINFELD <u>Disposition of Troops Duri</u> <u>Unit</u> 2826th Engr C Bn 2827th Engr C Bn 2828th Engr C Bn 2828th Engr C Bn	I constructions. repai Type Leth loating Tread 96' Treadway 132' Ing Period. Task Building House Trains Building House Trains 100th Inf Div. Com Working atrport, 1 abatis, supporting Checking VI Corps supporting the lot 2 er 50' 40 2 REI	<u>r and maintenance.</u> <u>cl Lanes & Comp Date Comp.</u> 40 1 Removed 40 1 Removed aller for VI Corps, supporting astructed Timber Bridge. removing treadway bridge, clearing 103rd Inf Div. bivouac area, removing road block th Armd Div. <u>& comp Date Comp.</u> 100 222400B

SECRET



<u>SECRET</u>	
ENGINEER SITUATION REPORT Auth: CO 36 Engr 60 Init: /201 Date: 24 April 1945	
2400 B Hours 23 April 1945. Geriod Cove d: From: 222400 B To: 232400 B	
 ADMINISTRATION. A. Head quarters reporting: <u>36th Engineer Combat Group</u> Coordinates: <u>262068</u> Vic <u>KIRCHHEIM</u> B. <u>Change in status or location of Battalions or companies:</u> <u>2826th Engr Bn</u>: Bn Hqs and H&S Co. moved to 265067 vic <u>KIRCHHEIM</u>. "A" Co. moved to 268093 vic NOTZINGEN. "B" Co. moved to 316101 vic SCHLIERBACH. "C" Co. moved to 270093 vic NOTZINGEN. <u>2828th Engr Bn</u>: "A" Co. moving. "B" Co. moved to 478668 vic EHINGEN. "C" Co. moved to 384721. 	
II. <u>INFORMATION ON OBSTACLES ENCOUNTERED</u> . A. <u>Bridges or culverts:</u> Spans Wet <u>Coord. Vicinity Crossing Type Lanes Cl Ho Lgth Gap Gap</u> 238133 PLOCHINGEN Neckar Concrete 2 40 2 150' 300' 140' 235120 PFAUHAUSEN Neckar Concrete 2 40 3 105! 180' 95' 37' 37'	
 (1) 2 blows 150' each. (2) one span 105' and 2 spans of 37' each, blown. B. Road Blocks. Coordinates 242128 Wood, concrete and steel Removed 249140 Timber road block Removed 240151 Timber road block Removed 202202 Timber road block Removed 2571.50 Timber road block Removed 241187 Timber road block Removed 240194 Abatis road block Removed 	
III. <u>OPERATIONS</u> . B. <u>Roads</u> . <u>2827th Engr Bn</u> maintaining road from 239134 PLOCHINGEN to 197250 ENDERBACH and from ENDERBACH to 269137 RIECHBACH, filling in pot holes, shell craters, and removing vehicles from road. Maintained road from LORCH. 431238 to GOPPINGEN 405140, road is in poor shape. <u>2828th Engr Bn clearing</u> debris from road FRANKENHOFEN 383721 to EHINGEN 470670.	
 A. Bridge, bypass, or ford-construction, repair and maint. <u>Coord. Vicinity Type Lgth Cl Lanes %Com Date Com</u> 400765 HUTTEN two Culverts 100 232400B E. Disposition of Troops During Period. 	1
L. <u>Disposition of Troops During Period</u> . <u>Unit</u> 2826th Engr C Bn - Constructing house trailer for VI Corps, moving, supporting 100th Div.	
2827th Engr C Bn - Road maintenance, maintaining air strip, removing road blocks, sup- porting 103rd Div.	

- 1 -



1. 36 211

<u>S E C R E T</u>

E. <u>Disposition of Troops During Period (Cont'd)</u>. Unit <u>Task</u> .2828th Engr C Bn - Road clearance, constructing culverts, supporting 10th Armd Div. 10001110 CONTROL LAND TO T Inclosures: ____ Bridge Recon Report ____ Road Overlay. Incrosure 11dan ... and and RALPH G. GODFREY Captain, 36th Engr C Group S-3 ्रियो प्रदेश के में संदर्भाषा /ewh shirts a roog whole initia roor arta 1 na circan arta den forsteren and start 会成了不可做。 The second state that the states with - way of .15 · · ······· . T ... 211 10 2 1001 3 55 00001928 3 19 $\begin{array}{c} \left(\left(1 + \frac{1}{2} \right)_{i=1}^{n-1} \right) & = \\ \left(\left(1 + \frac{1}{2} \right)_{i=1}^{n-1} \right)_{i=1}^{n-1} \left(\left(1 + \frac{1}{2} \right)_{i=1}^{n-1} \left(1 + \frac{1}{2} \right)_{i=1}^{n-1} \left(\left(1 + \frac{1}{2} \right)_{i=1}^{n-1} \left(1 + \frac{1}{2} \right$ 19.94 3612 -SECRET Sea00. 3 Aller and an aller and a second The state and the second second second



ENGINEER SITUATION REPORT

1

<u>S E C R E T</u> Auth: CO 36 Engr Gp Init: Date: 25 April 1945

Station of the local division of the local d	DO B		hours	24 April	1945	
riod	Covered:	From:		400 B	To:	242400 B
14.12			Map Hor: 2	S and X 1:10	00,000.	
I.	ADMINIS	TION.				
A.	Headquart			36th I	ngineer Combat	
		ordinat		262068	Contraction of the International Academic Street and the International Academic Street	RCHHEIM
B.					talions or Com	
						8. "A" Co. moved to
	479772. 1	B" Co.	moved to	481771. "C	" Co. moved to	595611.
	S	-				
II.	OPERATIONS	3.	-			
B.	Roads.					
	2826th Er	ngr Bn	improving	, removing	debris and wid	ening for two way traff
						00938 vic SCHLATTS VALL
						0862 and south and east
						Engr Bn clearing high-
						o 620750. Clearing
						ters at 625755 and 5056
D.			ngineerin			
					e around barra	cks used for displaced
529						etedstimated time of
						orps. D-7 digging in
	radar and	d gun r	ositions	for 216th 4	44 Bn. 2827th	Engr Bn cut 60 trees
						832na Avn. Engrs.
					ea for mines a	
Ε.				ring Period		
	and a subscription of the	nit	1100pb Du	ing fortou	• Tas	۶.
	2826th Er		n -	- Pond ma		structing trailer for
	LOLOGII III	TET O D				radar and gun positions
						arracks with barbed wir
	DOODLL TH				ing 100th Div.	
	2827th Er	igr C B	n			t, supporting 103rd
	000044				eparing to mov	
	. 2828th	or U B	n			cking for mines, moving
			and the state of		ing 10th Armd	
	Group Hqs	5		- Driver	on T/D with VI	. corps.
				· 40	5	
IV.	EQUIPMENT	Contraction of the local division of the loc	and the second se		Real and a strength	
de.			operatio		0	Mars Out at it as
	Coordinat	and the second se	Vicinity		and desserve and a second s	Hox Quantity
No. al	262066		IRCHHEIM	Creek	Clear	15 GPM output
C		n statu	Constitution and a state of the second state o	r equipment		
	Org.	12	Item	Carte	Disposition	
			Prime Mov	er	469th Engrs	Repairs
	2826th E	D-7	Tractor	The second	469th Engrs	Repairs
					Valle	al A Mart
					1han	a for the per
				1	RALPH G.	GODFREY
		-1-			a	D D D

Captain, 36th Engr C Group

/ewh

NARA, Dal



MANA

Peri

I

II

III

	<u>SECRET</u>
	ENGINEER SITUATION REPORT Auth: CO 36 Engr G Init: R. S. H. j"
	Init: R. S. H. J".
	Date: 26 April 194
24	00 B Hours 25 April 1945.
.od	Covered: From: 242400 B To: 252400 B
	ADMINISTRATION.
Å.	Headquarters reporting: 36th Engineer Combat Group
	Headquarters reporting: <u>36th Engineer Combat Group</u> Coordinates: <u>518810</u> Vic <u>BLAUBERUREN</u>
в.	Change in status or location of Battalions or Companies:
	2826th Engr Bn: Bn Hqs and H&S Co. moved to 663832 vic
	ULM. "A" Co. moved to 599939 vic LUIZHAUSEAL. "B" Co. moved to 645867 vic DORNSTADT. "C" Co. moved to 630876 voc DORN-
	STADT. 2827th Engr Bn: Bn Hqs moved to 557045 vic GEIS-
	LINGEN. "A" Co. moved to 550050 vic GEISLINGEN. "B" Co.
	moved to 553050 vic GEISLINGEN. "C" Co. moved to 550043
1	Vic GEISLINGEN. Group Hqs: moved to 518810 BLAUBERUREN.
	2828th Engr Bn: "A" Co. moved to 660770 vic AMERSTETTEN. "B" Co. moved to 734596 vic DIETENHEIM. "C" Co. movel to
	697595 vic HORENHAUSEN.
Γ.	INFORMATION ON OBSTACLES ENCOUNTERED.
в.	Road Blocks.
	Coordinates Type Disposition 7 662228 Abatis Removed
670	662828 Abatis Removed
Γ.	OPERATIONS.
A.,	Bridge, bypass, or ford construction, repair and maint.
	Coord. Vicinity Type Lgth Cl Lanes %Com. Date Com. 744593-DIETENHEIM-F1. Tread. 168' 40 1 100 250200B
T	Deede
в.	Roads. 2826th Engr Bn cleared debris and repaired road at 645867
	vic DORNSTADT, using D-7 tractor. Two truck loads of gravel
	used, work completed. 2827th Engr Bn maintaining roads
	from 420128 vic GOPPINGEN to 540050 vic HEISLINGEN to 610-
	964 vic LONSEE, clearing partial road blocks, removing trees and vehicles, and filling holes. Road from GEISLINGE
	to LONSEE is class A, but requires continual maintenance
	at spot where road blocks were removed.
D.	Miscellaneous Engineering Work.
	2826th Engr Bn stringing hurbed wire ground harrocks used

2826th Engr Bn stringing barbed wire around barracks used for displaced persons at 448138 vic GOPPINGEN, work completed 251500B. Used 8 rolls of barbed wire, 40 rolls of concertina, and 65 timber posts for entire job. Checked 4 buildings for 538th QM for mines and booby traps. No mines found, work completed. <u>2827th Engr Bn</u> alerted "C" Co. to build bridge over Danube river as of 251400B. <u>2828th Engr</u> Bn standing by to put in 100" Bailey bridge at 728664 vic ILLERRIEDEN. Attempt was made to build the bridge but enery artillery was too concentrated, some bridging equipment was damaged. At 250420B an enemy convoy attempted crossing the



. .

C

Π	Miscellaneous Engineering Work (Cont'd).
	bridge at 744593. It consisted of prime mover, one 88mm
	gun, two 2 1/2 ton trucks, one passengor car, three 20mm
	guns, and one motorcycle. In the resulting action the
	damage to the enemy was 3 dead, 4 wounded, and 30 captured
E.	Disposition of Troops During Period.
	Unit Task
	Unit 2826th Engr C Bn - Constructing trailer for VI Corps,
2 - Q."	clearing and repairing road, en- closing barracks with barbed wire,
	removing road block, operated vehicl
:	check point vic 270075 from 241800B
1.1	to 250700B - point closed, moved.
	2827th Engr C Bn - Road maintenance, supporting 103rd
	Div, alcrted to build bridge, moved.
	2828th Engr C Bn - Bridge construction, supporting 10th
	Armd Div, moving.
	Group Hqs - Driver on T/D with VI Corps.
1 (A)	dioup ndb - bilver on i/b with vi corps.
TV.	EQUIPMENT AND SUPPLIES.
A .	Water points in operation.
111	<u>Coordinates</u> Vicinity Source Quality Total Outret 26:066. KIRCHHEIM Closed 9,730 Cal.
C.	Change in status of major equipment.
	Org. Item Cause Disposition Action Require 2826th E 2 72 T Air Comp. Bn Shop Repairs
1.1.1	Locom h 2 /2 i All Comp. Dh Shop Repairs
T.J. *,	
	Rayh J. Hod frey P. RALPH G. GODFREY
	RALPH G. GODFREY
	Cuptain, 36th Engr C Group
	S-3
	/ewh
	- 80 017540, 2014
	There is not seen a set of the second s
	A REAL PROPERTY OF A READ
B*.	
100	
11.10	
1.1.2 GA2.	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Charles Sectors Sectors Sectors
	Contraction of the second states and the sec
	- 2 -
and a start	SECRET

- 2 -<u>S</u><u>E</u><u>C</u><u>R</u><u>E</u><u>T</u>



<u>S</u>ECRET

2 0 8 1

ENGINEER SITUATION REPORT <u>ENGINEER SITUATION REPORT</u> Muth: CO 36 Engr Gu Init: / Date: 27 April 1945 <u>2400 B</u> <u>Period Covered: From: 252400 B</u> To: 262400 B

- I. ADMINISTRATION.
- A. Headquarters reporting: 36th Engineer Combat Group Coordinates: 518810 Vic BLAUBEUREN
- B. Change in status or location of Battalions or Competants: 2826th Engr Bn: Bn Hqs and H&S Co. moved to 665823 vic ULM. 2827th Engr Bn: "A" Co. moved to 733865 vic ELCH-LINGEN. "B" Co. moved to 743847 vic LEIBI. "C" Co. moved to 733865 vic ELCHLINGEN.
- II. INF MATION ON OBSTACLES ENCOUNTERED. B. Road Blocks.

Road Blocks.					
Coordinates	Vicinity	Type		Disposition	
537030	GEISLINGEN	Abatis		Removed	
662828	. ULM	Abatis		Removed	
655306	ULM	Abatis		Removed	
741851	LEIBI	Log - mined	it.	Removed	
742850	LEIBI Blo	w 40' wide X	10' deep	Filled	

III. OPERATIONS.

TA.

A .	Bridge,	bypass, or	ford cons	struct	tior	i, repa	air & r	paintonanco	
	Coord.	Vicinity	Туре	Lgth	Cl	Lanes	%Comp	Date Com	
	524804	BLAUBEUREN	Timber	51'	40	2	10	271800B	
		LEIBI Fl.					100	261830B	
	728663	ILLERRIEDEN.	-Bailey T/	/S-100)'-4	10-1	100	260330B	

B. <u>Roads</u>. <u>2826th Engr Bn</u> widening road for two way traffic at 645-867 vic DORNSTADT. Widening bypass for two way traffic from 615820 vic EHERENSTEIN to 606825 vic KLINGENSTEIN. 15 loads of gravel used for above road improvement.

- D. <u>Miscellaneous Engineering Work</u>. <u>2826th Engr Bn</u> filled crater at 325942 vie SCHOPPLOCH. Constructing trailer for VI Corps. Clearing debris from streets in ULM, using two D-7 tractors. <u>2827th Engr Pn</u> worked on approaches to bridge at 742849 vie LEIBI.
- E. <u>Disposition of Troops During Period</u>. Unit

100	· 것은 가장 같은 것 <mark></mark>	
	2825th Engr C Bn - Filling craters, removing road blocks	
	constructing fixed bridge, building	
	trailer for VI Corps, clearing street	
	of debris in ULM.	
	282"th Engr C Bn - Constructing Treadway bridge, moved,	
	removed road blocks, supporting 103rd	
	Div.	
	2828th Engr C Bn - Constructed Bailey bridge, supporting	
	10th Armd Div.	

-l-SECRET



<u>SECRET</u>

The star Bar I a

2

Water points in operation. IV. EQUIPMENT AND SUPPLIES. A. Coordinates Vicinity Source Quality Max Quantity 617820 EHRENSTEIN Creek Clear 15 GPM

 Change in status of major equipment
 Orget
 Item
 Cause
 Disposition
 Action Req

 2826th E
 (2) 3/4 T W/C
 (new vehicles issued)
 T
 T

 2826th E
 1/4 T C&R
 Bn Shop
 Reprine

 C. RALPH G. GODFREY Captain, 36th Engr C Group S-3 57 ** B.* MOLLON! SC PLACE 117. . 145020 145020 157021 1297020 the support of the state of the . 56 . 18 1 20 0 7.0 Liston gozineg: terti 50 C 2 5 . . The second second second - 2 -1.1.2 SECRET



ENGINEER SITUATION REPORT Auth: CO 36th FA

0.4	OO B Hours 27 April.	1945.
Period	OOB Hours 27 April. Covered: From: 262400 B	To: 272400 B
I. A.	ADMINISTRATION.	36th Engineer Combat Gp
17.4	Headquarters reporting: Coordinates: 518810 Change in status or location of	VIC. BLAUBEUREN
В.	Change in status or location of	Battalions or Companyons
	2826th Engr C Bn: Bn Hqs moved 1 Co. moved to 045490 vic HAUSEN.	"B" Co moved to 9564 Vic
	of KRUMBACH. "C" Co. moved to 8	348743 vic WALLENHAUSEN.
ş		to 053425 vic MINDELHEIM. "B" Co 050423.
II. B.	INFORMATION ON OBSTACLES ENCOUNTR Road Blocks.	SKED.
D.	Coordinates Vicinity Ty	pe Disposition
	947645 KRUMBACH Aba	atis Removed
III:	OPERATIONS.	
Aį	Bridge, bypass, or ford constru	
•		Cl Lanes % Comp Date Comp
	524804 BLAUBEUREN Timber 51' 605826 KLINGENSTEIN Timber 48'	
	600825 HERRLINGEN Timber 30'	40 2 100 271.330
	742849 LEIBI Fl Tread.216'	40 1 Maintenance
в.	Roads.	
	282%th Engr Bn removed dead hor or. 2826th Engr Bn clearing and	
• •	676795 vic ULM south to 750645	
D.	Miscellaneous Engineering work.	
	2826th Engr Bn removing debris	and enemy vehicles from
	streets in UIM. Used three D-7	Tractors. Constructing
	trailer for VI Corps. Road rec and from ULM to MEMMINGEN, south	heast to OTTOBEIIREN. From
Charles St.	ULM east to GUNZBURG. 2827th E	ngr Bn constructing boom for
	Floating Mines and debris at br	idge site LEIBI 741851.
ilab E.	DISPOSITION OF TROOPS DURING PE	
	Unit 2826th Engr C Bn	Constructing Dived Dridge
	LOLO MI MIGI O DI	Constructing Fixed Bridge: Building Trailer for VI
		Corps, Clearing streets of
		debris in ULM, road maint
	797	Removal of aerial bombs &
I. G.	THETHER L FREENET DEPENDENCE	operating generator for V Corps Hqs.
	2827th Engr C Bn	Removed abatis and dead
		horses from roads, bridge
1		maintenance and boom con-
		struction. Supporting 10 Inf Div.
	2828th Engr C Bn	Supporting 10th Armd Div
		and moving.
	-1-	



Sesapp Jude o DE

§ I. C. Engineer Personnel Casualties. EM

Share & Barrish	EM	的問題相任	ing synctrop	GALLON .
		Menova	L of corial	· pompa v i
the state of the s		TODETT	TH ATTAL	Ser man
		001/14	17111/0	shi ar o
1		BING	18/ Linker	TOTAT
State State State	S850 the music C lon .	· RALPI	I G! GODFRE	Y TREFORMENTS
	THIE		36th Engr	
/jwp S*	DISPOSITION OF ANDLE DESING FEB		S-3	
/ JAP				2 .
San	Floating mines in debris it bri	der ditte	PLITER AND	BU AN INT
	MULL Seat to CUMBUIG. 282744-MM	er Br o	ostatisrochtun	p000 10.
	dance elizabilition of MEU dor't bac	elaet to	OTTO DEMONSTR	·於《翻集/342》(
	trail / for VL Corpu Hond rico	n rrom	TIME CONTRACT	O. SHERE
AND CANADA	stroots in ULL. Used throu De?	(13)-11 (0-12 (0.1.)	e. Constra	9.4771110
	TO DESCRIPTION OF A CONTRACTOR OF A DATA	nd cher	A WATCHER	1.1.00
	Miscellaneous Surfausting NOTS	and the second		
	CTERTON AL LEVON LIV DIV 207575	re phiri	aloff hat "	· 1 · 1 · 1 · · · · · · · · ·
A Charles and and	OT. DECOMPTINT BY CLEARING MAG	「日本のため」」	हिंदी के के कि कि कि कि कि कि	LOIC DI LI
and the second	26275h Engy Ph removed dead hour	on thank	read in th	GIL BOOL
Ba	Zoada		· · · · · ·	No.
	-742849 LUIBI	0 I.	- Mainteran	Q. C.
and the stand of the stand	m600625 Har Line 11 House Stander SQL 4	0 5	téo s	SISHO
	- 202859 - LITAL CONTRACTOR AND	0. 5.5	JUO S.	STYND
A Lord & Recht	254804 LIVING IN ITUDET DTI &	0 500	Too S.	150.00
	COOPA. VI HILL CYPA LEVEL O	T. THING	+ 10 CORD. T	THE REAL OF D
ALL	Bridge, oround, or ford construct	STOUP L	DOTI & EUT	uceduneq.
TIT	OPERATIONS.			
and the second	and the second		and a second for	1917日11日
	ga7645 ICUDEAdu - Laba	orn in	Bano	A REAL PROPERTY.
a la francisca de la composición de la	and a second			「消費権のその主
	Coordination VICINICA		Brub	ouratou l
	Road Blocks.		and the second sec	
II.	INFORMATOR C. CUTTOLES ENGORIZE	TTT: DE	and a standard of	
			00 020452	·
	288344 Ener C II: The Had moved			
1. 自己的 1. 1	of KEUNBACH. "ID COVED to Pu	54 641.R	G DEPENDING	A Particle
	A STATE STATE AND AND A STATE A ST	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	where the set is set in	ALCONTRACT BOOM
	Coordinates: Dicolo Change in status or icontion of h 2826th Ervi C But Ba sigs moved to	A Pach I	TO RECEIVE	32 Be
E.	Change in bratus or location of b	C'OCCUTTO	ue or nomb.	
		TOT.	amentaneros	1. Commence
		SP.00	mariena di	· · · ·
Contraction In the second	VDMINISLEVLION.	in a les	and the second	
101100	Covered: Prome 27 April	10: 15	ISTON A	and materies and a second
5.41	CO B Hours 27 Abota	an and and a second second second	Talat.	
			4 W 11 W	
		. State	Salaan: 50	Thr.
The Participants			- jourgen : SR	
	<u>SECRET</u>	- 13 12 C	NAL PALE	20.41

19.63

1

1

N. .

and maying.

Supporting 1014 Arnd Div

horses Crop rolds, bridge maintenance and book denstruct on. Supporting 10 int 217.

(KIA): Fre (WIA) 011 mpt W 3. House Los A



ENGINEER SITUATION REPORT

SECRET Auth: CO 36 Engr Init: Date:: 29 April 1945

2400 B 28 April 1945 Hours 272400 B Period Covered: From: 282400 B Tor

- I. ADMINISTRATION.
- A. Headquarters reporting: <u>36th Engineer Combat Group</u> Coordinates: <u>168128</u> Vic <u>MARKT OBERDORF</u>
- Change in status of location of Battaldons or Companies: B. 2826th Engr Bn:: Bn Hqs moved to 160130 vic MARKT OBERDORF. "B" CO. moved to 155238 vic KAUFBEUREN. "C" Co. moved to 160130 vic MARKT OBERDORF. 2827th Engr Bn: Bn Hqs moved to 213180 vic BERNBACH. "A" Co. moved to 257127vic RETTENBACH. "B" Co. Moved to 345196 vic ALTENSTADT. "C" Co. moved to 256126 vic RETTENBACH. 2828th Engr Bn: Bn Hqs and """ Co. moved to 365175 vic SCHONGAU. Group Hqs. moved to 168128 vic MARKT OBERDORF.

III. OPERATIONS.

B. Roads.

2826th Engr Bn clearing and improving road stretch from 676796 vic UIM south to 822 822350 vic MEMMINGEN east to 048421 vic MINDELHEIM.

D. Miscellaneous Engineering Work.

2826th Engr Bn filling in bomb craters and repairing landing strip at 860360 vic MEMMINGEN, work completed 271000B. Filling bomb craters and repatring landing strippatg150240 vic KAUFBEUREN. 2827th Engr Bn repaired bridge at KRUMBACH, placing planking on floor. Removed demolitions at 919654. Made reconnaisance of br bridge site at 298042 vic FAICHEN, preparing to put in Treadway bridge.

E. Disposition of Troops During Period.

Unit

Task

- 2826th Engr C Bn - Road clearance, repaing landing strips, building trailer for VI Corps. 2827th Engr C Bn - Repaired bridge, removed demolitions, moved, supporting 103rd Inf Div. 2828th Engr C Bn
 - Supporting 10th Armd Div.

b RALPH G. GODFREY Captain, 36th Engr C Group 5-3

SECRET

Cardin Barrison and State	
DECLASSIFIED	
735017	
MARA Data	
PUVIA, Data	SECRET
	SECRET
	ENGINEER SITUATION REPORT Auth: CO 36 Engr Go
	Init:
	Date: 30 April 194
211	00 B Hours 29 April 1945.
ariod	Covered: From: 282400 B To: 292400 B
31104 ·	
I	ADMINISTRATION.
A.	Headquarters reporting: <u>36th Engineer Combat Group</u> Coordinates: <u>168128</u> Vic MATKT OBERDORF
	Coordinates: 168128 Vic MARKE OBERDORF
В.	Change in status or location of Battalions or Companies:
	2826th Engr Bn: "A" Co. moved to 157242 vic KAUFBEUREN.
	2827th Engr Bn: Bn Hqs moved to 295047 vic LECHBRUCK. "B"
	Co. moved to 345052 vic STEINGARTEN. 2828 th Engr Bn: "B" Co. moved to 376171 vic SCHONGAU. "C" Co. moved to 230900
	vic FUSSEN.
A State State State	AIG TODDEW.
II.	INFORMATION ON OBSTACLES ENCOUNTERED.
	Road blocks.
	Coordinates Type Disposition
	165145 Abatis Removed
	165154 Abatis Removed
一心必要无能。這一	208801 Abatis Removed
A Cashe and an	242938 Abatis Removed
1 Aller and a start	Ol0204 Abatis Removed
	203872 Unknown Removed
III.	OPERATIONS.
	Bridge, bypass, or ford construction, repair & maintenance,
	Coord. Vicinity Type Lgth Cl Lanes %Comp Date Comp
	299042 LECHBRUCK-F1. Tread 132' 40 1 100 291130B
	370171 SCHONGAU Bailey 110' 40 1 -100 290100B
- Spiele and state	371171 SCHONGAU Fl. Tread 204! 40 1 100 290900B
	228890 FÜSSEN Bypass (Relieved by 55th Engrs 291400B)
, В.	Roads.
N. S. S. S. S.	2826th Engr Bn clearing, improving, and removing vehicles
and the second second	from road stretch from 153243 vic KAUFBEUREN to 008205 vic
	OBER GUNZBURG. 2827th Engr Bn maintaining MSR from MARKT OBERDORF 160130 to SCHONGAU 366175 and clearing vehicles
	off-road.
D.'	Miscellaneous Engineering Work.
a di se a di s	2826th Engr Bn guarding warehouse containing ponton bridg-
	ing equipment and rubber boats at 164233 vic KAUFBEUREN.
	2827th Engr Bn maintaining approaches to Treadway bridge
	at LECHBRUCK. "A" Co. assault landed infantry across river
₹4.	
Ε.	Disposition of Troops During Period.
	Unit DECTORE
	2826th Engr C Bn - Removing road blocks, clearing roads
	guarding warehouse, building trailer
	2827th Engr C Bn - Constructed Treadway bridge, 1 nded
and the second	infantry across river, maintaining
	roads, moved, supporting 103rd Div.
	2828th Engr C Bn - Constructed bridges, removed road
	blocks, supporting 10th Armd Div.
	-1-

. .





SECRET Auth: 00 36 Engr G ENGINEER SITUATION REPORT Init: Date: 1 May 1945. 19:5. 30 April 2400 B Hours eriod Covered: From: 292400 B To: 302400 B I. ADMINISTRATION. Headquarters reporting: <u>36th Engineer Combat Group</u> Coordinates: <u>263891</u> Vic HOHEN SCHWANGAU Change in status or location of Battalions or Companies: A . в. 2826th Engr Bn: Bn Hqs and H&S Co. moved to 228892 vic FUSSEN. "A" Co. moved to 188904 vic OBERRIED. "B" Co. moved to 258908 vic SCHWANGAU. "C" Co. moved to 250895 vic FUSSEN 2827 th Engr Bn: Bn Hqs and "C" Co. moved to 545852 vic GARLISCH PARTENKIRCHEN. Group Hgs: moved to 263891 vic HOHEN SCHWANGAU. INFORMATION ON OBSTACLES ENCOUNTERED. II. Road blocks. В.. Vicinity Coordinates Disposition Type Debris removed 250778 KLAUSEN Blown overpass II. OPERATIONS. Bridge, bypass, or ford construction repair and maint. Coord. Vicinity Type Lgth Cl Lanes %Comp Date Comp · A . 299042 LECHBRUCK Fl. Tread 132' 40 1 Maintenance 450040 SOLENER Timber 15' 40 1 100 30140 371171 SCHONGAU Bailey 110' 40 1 Maintenance 373173 SCHONGAU Fl. Tread 210' 40 1 Maintenance 1 100 301400B 373173 SCHONGAU F1. Tread 210'-40 1 Maintenance 590823 KALTENBRUNN Treadway 36' 40 1 100 301200B 600823 KALTENBRUNN Bailey D/S-80'-40-1 Preparing to put in 282757 HEITERWANG Treadway 36' 40 1 100 301400B 294745 BICHLBACH Bailey D/S 60' 40 1 100 * 12 282756 HEITERWANG Timber 36' 40 1 Preparing to put in Roads. В. 2827th Engr Bn cleared road from 430064 vic SCHWAIG south to 545852 vic GARMISCH PARTENKIRCHEN. Cleared road from 348054 vic STEINGADEN to 432064 vic SCHWAIG. Filled croter at 433060 vic SCHWAIG. 2828th Engr Bn repairing crat on far approach to existing bridge at 432064. Filling in crater at 449041. Filling in 30' crater at 590823. Miscollaneous Engineering Work. D. 2826th Engr Bn checking VI Corps area for mines and booby traps at 346045 vic STEINGADEN, no mines found. 8 men guarding warehouse at 164233 vic KAUFBEUREN, relieved at 3014 OB. Road reconn from 230892 vic FUSSEN south to RJ at 377718 vic LERMOOS, northeast to 540830 vic GARMISCH PAR-TENKIRCHEN east to 599824 vic KALTENBRUNN. Road reconn from 230896 vic FUSSEN northwest to 946046 vic KEMPTEN, and from 230892 vic FUSSEN northeast to 370170 vic SCHONGAU. Road stretch from 230892 vic FUSSEN south to RJ at 377718 vic LERMOOS clear, results on rest of reconn unknown.

- 1

ALINNA, L	we we also the reaction of reaching them.
	SPONS ALG LARGE SOUL STREET
E.	Disposition of Troops During Period. Unit
	2820 th Engr C Bn - Constructing trailer for VI Corps, guarding warehouse, road reconn and clearance, removing road block,
	2827 n Engr C Bn - Bridge construction and maintenance rold maintenance, supporting 103rd
	2828th Engr C Bn - Constructing bridges, road mainten- ance, supporting 10th Armd Div.
	EQUIPMENT AND SUPPLIES. Water points in operation. Coord. Vicinity Source Quality Max Quantity 157250 KAUFBEUREN Creek Clear 15 GPM
c.	Change in status of major equipment. Org. Item Cause Disposition Action I - Couse Disposition Action
	2828th EPrime mover264th Ord. Repairs2828th E242 T Dump Broken BubbyBn Shop Repairs2828th E242 T Dump ClutchBn S.op Repairs2828th E242 T Dump Center BoltsBn Shop Repairs2828th E242 T Dump Center BoltsBn Shop Repairs2828th E242 T Dump Hole in gas tank Bn Shop Repairs
	CIERCE CONTRACTOR DE CONTRA
	R.LPH G. GODFREY
	S-3
	/ewh
T.	TEARLING AND A COLLEGE AND AND A COLLEGE
	To a state of the second s
an an	SECRET



HEADQUARTERS 36TH ENGINEER COMBAT GROUP APO 758 U. S. Army

7 May 1945

SUBJECT: Letter of Transmittal.

TO : Commanding General, 7th Army, APO 758, US Army.

Submitted herewith are historical reports for the month of April 1945, for this Hqs and 2826th, 2827th and 2828th Engr C Bns.

MAY-8'45PM

For the Commanding Officer:

P

NGD

-36-0.2

Č1

Gaptain, 36th Engr C Group Acting Adjutant

4 Incls. Historical Reports.





HEADQUARTERS 36TH ENGINEER COMBAT GROUP APO 758 U.S. Army

7 May 1945

HISTORICAL REPORT FOR THE MONTH OF APRIL 1945

After just crossing the Rhine at Mannheim, the Group assembled in the vicinity of Seckenheim. Having no definite assignment for the first few days of the month, the Group engaged in training, maintenance of bridge approaches, road maintenance and reconnaissance.

The VI Corps push south and southeast started around 4 April and the battalions were again employed as combat engineers, by supporting the infantry and armor drives. The Heilbronn pocket delayed operations for approximately two weeks. The 2826th Engr C Bn maintained entrance and exit to dukw sites which supplied the bridgehead. The battalion also operated infantry support rafts during the period.

From 5 to 16 April Group hqs was located in Neckarzimmern where they located and kept a guard on the underground ball bearing factory located near the CP.

Around the 16th of the month enemy organized resistance began crumbling. The enemy retreated with haste often leaving bridges intact with demolition charges but no one to blow the bridge. In spite of the long hasty retreats the enemy did manage to catch his breath and employed his customary delaying acts, but the thoroughness previously encountered was lacking. However enough destruction was caused by the enemy to keep the battalions busy whenever they weren't moving. A decided decrease in minefields was noted for the period.

Moving took up most of our time. Group Hqs set up 9 different CPs during the month. The battalions and companies moved much more than that.

During the month the Group constructed 19 Timber bridges, 7 Baileys, 7 Treadways, and 2 Pontons. Our casualties were: 2 KIA: 13 WIA.

For the Commanding Officer:

JOHN G. ROESCHLAUB Captain, 36th Engr C Group Acting Adjutant

2 Incls. 1-Sitreps. 2-Operations Journal.